

ALERT: 26-9AQR - CRITICAL AOG

Hawker windshield heat failure

Bombardier Challenger 300 / 350 - PW600

Public Alert Information

STATUS

active

PRIORITY

CRITICAL

ICAO LOCATION

KATL

AIRCRAFT SERIES

Challenger 300 / 350

IMPACT TYPE

Charter

RTS TARGET

26SEP26 1445Z

ATA 100 CHAPTERS

5 - Time Limits / Maintenance Checks

13 Special Inspections

20 Standard Practices - Airframe

24 Electrical Power

SERVICE BULLETIN (SB)

Not specified

SHORT FAULT NAME

Hawker windshield heat failure

TROUBLESHOOTING STATUS

Troubleshooting Complete - All required Items listed

ROLES AND RESPONSIBILITIES

Responding provider supplies qualified personnel, material trace, and completion records.

ALERT TYPE

AOG Alert

ADDED TO PLATFORM

16SEP26 1445Z

AIRCRAFT MODEL

Bombardier Challenger 300 / 350

ENGINE MODEL

PW600

MX WINDOW OPENS

25SEP26 1445Z

ALERT SPECIFICS

Unscheduled Maintenance

AIRWORTHINESS DIRECTIVE (AD)

Not specified

CHECK

Not specified

ERROR / FAULT INDICATIONS

Development scenario: Hawker windshield heat failure; aircraft is unavailable pending corrective action.

TSM/FIM REFERENCE

T330-008

Hawker windshield heat failure affecting a Bombardier Challenger 300 / 350; Development test data requiring coordinated recovery support.

Page 1 of 3

Items (4)

TESTING & CERTIFICATION - WANTED

Qty Not specified

Hawker windshield heat failure - support service 3

Item Id: H3RWU

Qualified technical support required for Hawker windshield heat failure.

PART / IPC REFERENCE	REQUIRED ONSITE
Not specified	25SEP26 1446Z
AIRCRAFT MODEL	ENGINE MODEL
Bombardier Challenger 300 / 350	Not specified
ATA 100 CHAPTERS	CONDITION
13 Special Inspections	Not specified
TRACE	RELEASE DOCUMENTATION
Not specified	Not specified

MAINTENANCE SERVICES - WANTED

Qty Not specified

Hawker windshield heat failure - support service 2

Item Id: WA7AF

Qualified technical support required for Hawker windshield heat failure.

PART / IPC REFERENCE	REQUIRED ONSITE
Not specified	25SEP26 1446Z
AIRCRAFT MODEL	ENGINE MODEL
Bombardier Challenger 300 / 350	Not specified
ATA 100 CHAPTERS	CONDITION
5 - Time Limits / Maintenance Checks	Not specified
TRACE	RELEASE DOCUMENTATION
Not specified	Not specified

LOGISTICS & CUSTOMS - WANTED

Qty Not specified

Hawker windshield heat failure - support service 4

Item Id: AEQ3G

Qualified technical support required for Hawker windshield heat failure.

PART / IPC REFERENCE	REQUIRED ONSITE
Not specified	25SEP26 1446Z
AIRCRAFT MODEL	ENGINE MODEL
Bombardier Challenger 300 / 350	Not specified
ATA 100 CHAPTERS	CONDITION
20 Standard Practices - Airframe	Not specified
TRACE	RELEASE DOCUMENTATION
Not specified	Not specified

Hawker windshield heat failure - replacement component 1

Item Id: EUPCN

Traceable replacement material required for Hawker windshield heat failure.

PART / IPC REFERENCE	REQUIRED ONSITE
T330-AOG-BIZ-3-1	25SEP26 1446Z
AIRCRAFT MODEL	ENGINE MODEL
Bombardier Challenger 300 / 350	Not specified
ATA 100 CHAPTERS	CONDITION
24 Electrical Power	Not specified
TRACE	RELEASE DOCUMENTATION
Not specified	Not specified

Status Updates (0)

No visible Status Updates.