ALERT: 26-M3RH - CRITICAL AOG

WANTED

Bell 412 hydraulic system failure - replacement component 1

Item Id: KERN9

Parts & Rotables - Airbus Helicopters AS355 Ecureuil 2 / TwinStar - KATL

Item Description

Traceable replacement material required for Bell 412 hydraulic system failure.

Item Details

PART / IPC REFERENCE **T330-AOG-ROT-4-1**	ALTERNATE PART NUMBERS **Not specified**
QUANTITY **1**	REQUIRED ONSITE **30SEP26 1446Z**
REVISION **Not specified**	MANUFACTURER **Not specified**
MANUFACTURER TYPES **Not specified**	ACCEPTABLE MANUFACTURERS **Not specified**
AIRCRAFT MANUFACTURER **Not specified**	AIRCRAFT MODEL **Airbus Helicopters AS355 Ecureuil 2 / TwinStar**
ENGINE MANUFACTURER **Not specified**	ENGINE MODEL **Allison 250-C20/C30**
ATA 100 CHAPTERS 20 Standard Practices - Airframe	CONDITION **Not specified**
TRACE **Not specified**	RELEASE DOCUMENTATION **Not specified**
TRANSACTION TYPES **Not specified**	INCOTERM **Not specified**
ONSITE LOCATION TYPE **Hangar / Maintenance Facility**	SERVICE AREA **Not specified**
LEAD TIME **Not specified**	EXPORT READY **Not specified**
WARRANTY **Not specified**	WARRANTY TERMS **Not specified**