ALERT: 26-9AQR - CRITICAL AOG

Hawker windshield heat failure

Bombardier Challenger 300 / 350 - PW600

Public Alert Information

STATUS
active

ALERT TYPE
AOG Alert

PRIORITY
CRITICAL

ADDED TO PLATFORM
16SEP26 1445Z

ICAO LOCATION
KATL

AIRCRAFT MODEL
Bombardier Challenger 300 / 350

AIRCRAFT SERIES
Challenger 300 / 350

ENGINE MODEL
PW600

IMPACT TYPE
Charter

MX WINDOW OPENS
25SEP26 1445Z

RTS TARGET
26SEP26 1445Z

ALERT SPECIFICS
Unscheduled Maintenance

ATA 100 CHAPTERS
5 - Time Limits / Maintenance Checks
13 Special Inspections
20 Standard Practices - Airframe
24 Electrical Power

AIRWORTHINESS DIRECTIVE (AD)
Not specified

SERVICE BULLETIN (SB)
Not specified

CHECK
Not specified

SHORT FAULT NAME
Hawker windshield heat failure

ERROR / FAULT INDICATIONS
Development scenario: Hawker windshield heat failure; aircraft is unavailable pending corrective action.

TROUBLESHOOTING STATUS
Troubleshooting Complete - All required Items listed

TSM/FIM REFERENCE
T330-008

ROLES AND RESPONSIBILITIES
Responding provider supplies qualified personnel, material trace, and completion records.

Hawker windshield heat failure affecting a Bombardier Challenger 300 / 350; Development test data requiring coordinated recovery support.

Items (4)

TESTING & CERTIFICATION - WANTED

Qty Not specified

Hawker windshield heat failure - support service 3

Item Id: H3RWU

Qualified technical support required for Hawker windshield heat failure.

PART / IPC REFERENCE
Not specified

REQUIRED ONSITE
25SEP26 1446Z

AIRCRAFT MODEL
Bombardier Challenger 300 / 350

ENGINE MODEL
Not specified

ATA 100 CHAPTERS
13 Special Inspections

CONDITION
Not specified

TRACE
Not specified

RELEASE DOCUMENTATION
Not specified

MAINTENANCE SERVICES - WANTED

Qty Not specified

Hawker windshield heat failure - support service 2

Item Id: WA7AF

Qualified technical support required for Hawker windshield heat failure.

PART / IPC REFERENCE
Not specified

REQUIRED ONSITE
25SEP26 1446Z

AIRCRAFT MODEL
Bombardier Challenger 300 / 350

ENGINE MODEL
Not specified

ATA 100 CHAPTERS
5 - Time Limits / Maintenance Checks

CONDITION
Not specified

TRACE
Not specified

RELEASE DOCUMENTATION
Not specified

LOGISTICS & CUSTOMS - WANTED

Qty Not specified

Hawker windshield heat failure - support service 4

Item Id: AEQ3G

Qualified technical support required for Hawker windshield heat failure.

PART / IPC REFERENCE
Not specified

REQUIRED ONSITE
25SEP26 1446Z

AIRCRAFT MODEL
Bombardier Challenger 300 / 350

ENGINE MODEL
Not specified

ATA 100 CHAPTERS
20 Standard Practices - Airframe

CONDITION
Not specified

TRACE
Not specified

RELEASE DOCUMENTATION
Not specified

PARTS & ROTABLES - WANTED

Qty 1

Hawker windshield heat failure - replacement component 1

Item Id: EUPCN

Traceable replacement material required for Hawker windshield heat failure.

PART / IPC REFERENCE **T330-AOG-BIZ-3-1**	REQUIRED ONSITE **25SEP26 1446Z**
AIRCRAFT MODEL **Bombardier Challenger 300 / 350**	ENGINE MODEL **Not specified**
ATA 100 CHAPTERS 24 Electrical Power	CONDITION **Not specified**
TRACE **Not specified**	RELEASE DOCUMENTATION **Not specified**

Status Updates (0)

No visible Status Updates.