ALERT: 26-K3N3 - CRITICAL AOG

H135 tail-rotor gearbox alert

Airbus Helicopters H130 / EC130 - Allison 250-C20/C30

Public Alert Information

STATUS
active

ALERT TYPE
AOG Alert

PRIORITY
CRITICAL

ADDED TO PLATFORM
16SEP26 1445Z

ICAO LOCATION
KATL

AIRCRAFT MODEL
Airbus Helicopters H130 / EC130

AIRCRAFT SERIES
H130 / EC130

ENGINE MODEL
Allison 250-C20/C30

IMPACT TYPE
Charter

MX WINDOW OPENS
29SEP26 1445Z

RTS TARGET
30SEP26 1445Z

ALERT SPECIFICS
Unscheduled Maintenance

ATA 100 CHAPTERS
5 - Time Limits / Maintenance Checks
13 Special Inspections
20 Standard Practices - Airframe
24 Electrical Power

AIRWORTHINESS DIRECTIVE (AD)
Not specified

SERVICE BULLETIN (SB)
Not specified

CHECK
Not specified

SHORT FAULT NAME
H135 tail-rotor gearbox alert

ERROR / FAULT INDICATIONS
Development scenario: H135 tail-rotor gearbox alert; aircraft is unavailable pending corrective action.

TROUBLESHOOTING STATUS
Troubleshooting Complete - All required Items listed

TSM/FIM REFERENCE
T330-012

ROLES AND RESPONSIBILITIES
Responding provider supplies qualified personnel, material trace, and completion records.

H135 tail-rotor gearbox alert affecting a Airbus Helicopters H130 / EC130; Development test data requiring coordinated recovery support.

Items (4)

MAINTENANCE SERVICES - WANTED

Qty Not specified

H135 tail-rotor gearbox alert - support service 2

Item Id: 47ATW

Qualified technical support required for H135 tail-rotor gearbox alert.

PART / IPC REFERENCE
Not specified

REQUIRED ONSITE
29SEP26 1446Z

AIRCRAFT MODEL
Airbus Helicopters H130 / EC130

ENGINE MODEL
Not specified

ATA 100 CHAPTERS
24 Electrical Power

CONDITION
Not specified

TRACE
Not specified

RELEASE DOCUMENTATION
Not specified

PARTS & ROTABLES - WANTED

Qty 1

H135 tail-rotor gearbox alert - replacement component 1

Item Id: HQHPF

Traceable replacement material required for H135 tail-rotor gearbox alert.

PART / IPC REFERENCE
T330-AOG-ROT-3-1

REQUIRED ONSITE
29SEP26 1446Z

AIRCRAFT MODEL
Airbus Helicopters H130 / EC130

ENGINE MODEL
Not specified

ATA 100 CHAPTERS
20 Standard Practices - Airframe

CONDITION
Not specified

TRACE
Not specified

RELEASE DOCUMENTATION
Not specified

TESTING & CERTIFICATION - WANTED

Qty Not specified

H135 tail-rotor gearbox alert - support service 3

Item Id: TGTWC

Qualified technical support required for H135 tail-rotor gearbox alert.

PART / IPC REFERENCE
Not specified

REQUIRED ONSITE
29SEP26 1446Z

AIRCRAFT MODEL
Airbus Helicopters H130 / EC130

ENGINE MODEL
Not specified

ATA 100 CHAPTERS
5 - Time Limits / Maintenance Checks

CONDITION
Not specified

TRACE
Not specified

RELEASE DOCUMENTATION
Not specified

LOGISTICS & CUSTOMS - WANTED

Qty Not specified

H135 tail-rotor gearbox alert - support service 4

Item Id: KPQYQ

Qualified technical support required for H135 tail-rotor gearbox alert.

PART / IPC REFERENCE
Not specified

REQUIRED ONSITE
29SEP26 1446Z

AIRCRAFT MODEL
Airbus Helicopters H130 / EC130

ENGINE MODEL
Not specified

ATA 100 CHAPTERS
13 Special Inspections

CONDITION
Not specified

TRACE
Not specified

RELEASE DOCUMENTATION
Not specified

Status Updates (0)

No visible Status Updates.