ALERT: 26-4EPU - ROUTINE MX EVENT

Learjet landing-gear scheduled work

Beechcraft Hawker 400 / 400XP - PW600

Public Alert Information

STATUS
active

ALERT TYPE
MX Alert

PRIORITY
ROUTINE

ADDED TO PLATFORM
16SEP26 1445Z

ICAO LOCATION
KATL

AIRCRAFT MODEL
Beechcraft Hawker 400 / 400XP

AIRCRAFT SERIES
Hawker 400 / 400XP

ENGINE MODEL
PW600

IMPACT TYPE
Charter

MX WINDOW OPENS
19SEP26 1445Z

RTS TARGET
20SEP26 1445Z

ALERT SPECIFICS
Scheduled Maintenance

ATA 100 CHAPTERS
5 - Time Limits / Maintenance Checks
20 Standard Practices - Airframe
24 Electrical Power

AIRWORTHINESS DIRECTIVE (AD)
Not specified

SERVICE BULLETIN (SB)
Not specified

CHECK
Not specified

SHORT FAULT NAME
Learjet landing-gear scheduled work

ERROR / FAULT INDICATIONS
Development scenario: Learjet landing-gear scheduled work; aircraft is unavailable pending corrective action.

TROUBLESHOOTING STATUS
Troubleshooting Complete - All required Items listed

TSM/FIM REFERENCE
T330-002

ROLES AND RESPONSIBILITIES
Responding provider supplies qualified personnel, material trace, and completion records.

Learjet landing-gear scheduled work affecting a Beechcraft Hawker 400 / 400XP; Development test data requiring coordinated recovery support.

Items (3)

MAINTENANCE SERVICES - WANTED

Qty Not specified

Learjet landing-gear scheduled work - support service 2

Item Id: HWQ4D

Qualified technical support required for Learjet landing-gear scheduled work.

PART / IPC REFERENCE
Not specified

REQUIRED ONSITE
19SEP26 1446Z

AIRCRAFT MODEL
Beechcraft Hawker 400 / 400XP

ENGINE MODEL
Not specified

ATA 100 CHAPTERS
24 Electrical Power

CONDITION
Not specified

TRACE
Not specified

RELEASE DOCUMENTATION
Not specified

TESTING & CERTIFICATION - WANTED

Qty Not specified

Learjet landing-gear scheduled work - support service 3

Item Id: TCHWQ

Qualified technical support required for Learjet landing-gear scheduled work.

PART / IPC REFERENCE
Not specified

REQUIRED ONSITE
19SEP26 1446Z

AIRCRAFT MODEL
Beechcraft Hawker 400 / 400XP

ENGINE MODEL
Not specified

ATA 100 CHAPTERS
5 - Time Limits / Maintenance Checks

CONDITION
Not specified

TRACE
Not specified

RELEASE DOCUMENTATION
Not specified

PARTS & ROTABLES - WANTED

Qty 1

Learjet landing-gear scheduled work - replacement component 1

Item Id: AQQ9C

Traceable replacement material required for Learjet landing-gear scheduled work.

PART / IPC REFERENCE
T330-MX-BIZ-2-1

REQUIRED ONSITE
19SEP26 1446Z

AIRCRAFT MODEL
Beechcraft Hawker 400 / 400XP

ENGINE MODEL
Not specified

ATA 100 CHAPTERS
20 Standard Practices - Airframe

CONDITION
Not specified

TRACE
Not specified

RELEASE DOCUMENTATION
Not specified

Status Updates (0)

No visible Status Updates.