

ALERT: 26-M3RH - CRITICAL AOG

WANTED

Bell 412 hydraulic system failure - replacement component 1

Item Id: KERN9

Parts & Rotables - Airbus Helicopters AS355 Ecureuil 2 / TwinStar - KATL

Item Description

Traceable replacement material required for Bell 412 hydraulic system failure.

Item Details

PART / IPC REFERENCE	ALTERNATE PART NUMBERS
T330-AOG-ROT-4-1	Not specified
QUANTITY	REQUIRED ONSITE
1	30SEP26 1446Z
REVISION	MANUFACTURER
Not specified	Not specified
MANUFACTURER TYPES	ACCEPTABLE MANUFACTURERS
Not specified	Not specified
AIRCRAFT MANUFACTURER	AIRCRAFT MODEL
Not specified	Airbus Helicopters AS355 Ecureuil 2 / TwinStar
ENGINE MANUFACTURER	ENGINE MODEL
Not specified	Allison 250-C20/C30
ATA 100 CHAPTERS	CONDITION
20 Standard Practices - Airframe	Not specified
TRACE	RELEASE DOCUMENTATION
Not specified	Not specified
TRANSACTION TYPES	INCOTERM
Not specified	Not specified
ONSITE LOCATION TYPE	SERVICE AREA
Hangar / Maintenance Facility	Not specified
LEAD TIME	EXPORT READY
Not specified	Not specified
WARRANTY	WARRANTY TERMS
Not specified	Not specified