ALERT: 26-M3RH - CRITICAL AOG

Bell 412 hydraulic system failure

Airbus Helicopters AS355 Ecureuil 2 / TwinStar - Allison 250-C20/C30

Public Alert Information

STATUS
active

ALERT TYPE
AOG Alert

PRIORITY
CRITICAL

ADDED TO PLATFORM
16SEP26 1445Z

ICAO LOCATION
KATL

AIRCRAFT MODEL
Airbus Helicopters AS355 Ecureuil 2 / TwinStar

AIRCRAFT SERIES
AS355 Ecureuil 2 / TwinStar

ENGINE MODEL
Allison 250-C20/C30

IMPACT TYPE
Charter

MX WINDOW OPENS
30SEP26 1445Z

RTS TARGET
01OCT26 1445Z

ALERT SPECIFICS
Unscheduled Maintenance

ATA 100 CHAPTERS
20 Standard Practices - Airframe
24 Electrical Power

AIRWORTHINESS DIRECTIVE (AD)
Not specified

SERVICE BULLETIN (SB)
Not specified

CHECK
Not specified

SHORT FAULT NAME
Bell 412 hydraulic system failure

ERROR / FAULT INDICATIONS
Development scenario: Bell 412 hydraulic system failure; aircraft is unavailable pending corrective action.

TROUBLESHOOTING STATUS
Troubleshooting Complete - All required Items listed

TSM/FIM REFERENCE
T330-013

ROLES AND RESPONSIBILITIES
Responding provider supplies qualified personnel, material trace, and completion records.

Bell 412 hydraulic system failure affecting a Airbus Helicopters AS355 Ecureuil 2 / TwinStar; Development test data requiring coordinated recovery support.

Items (2)

PARTS & ROTABLES - WANTED

Qty 1

Bell 412 hydraulic system failure - replacement component 1

Item Id: KERN9

Traceable replacement material required for Bell 412 hydraulic system failure.

PART / IPC REFERENCE **T330-AOG-ROT-4-1**	REQUIRED ONSITE **30SEP26 1446Z**
AIRCRAFT MODEL **Airbus Helicopters AS355 Ecureuil 2 / TwinStar**	ENGINE MODEL **Not specified**
ATA 100 CHAPTERS 20 Standard Practices - Airframe	CONDITION **Not specified**
TRACE **Not specified**	RELEASE DOCUMENTATION **Not specified**

MAINTENANCE SERVICES - WANTED

Qty Not specified

Bell 412 hydraulic system failure - support service 2

Item Id: 7PGQG

Qualified technical support required for Bell 412 hydraulic system failure.

PART / IPC REFERENCE **Not specified**	REQUIRED ONSITE **30SEP26 1446Z**
AIRCRAFT MODEL **Airbus Helicopters AS355 Ecureuil 2 / TwinStar**	ENGINE MODEL **Not specified**
ATA 100 CHAPTERS 24 Electrical Power	CONDITION **Not specified**
TRACE **Not specified**	RELEASE DOCUMENTATION **Not specified**

Status Updates (0)

No visible Status Updates.