ALERT: 26-XKYV - CRITICAL AOG

Citation hydraulic pressure loss

Bombardier Learjet 60 - PW600

Public Alert Information

STATUS
active

ALERT TYPE
AOG Alert

PRIORITY
CRITICAL

ADDED TO PLATFORM
16SEP26 1445Z

ICAO LOCATION
KATL

AIRCRAFT MODEL
Bombardier Learjet 60

AIRCRAFT SERIES
Learjet 60

ENGINE MODEL
PW600

IMPACT TYPE
Charter

MX WINDOW OPENS
23SEP26 1445Z

RTS TARGET
24SEP26 1445Z

ALERT SPECIFICS
Unscheduled Maintenance

ATA 100 CHAPTERS
20 Standard Practices - Airframe
24 Electrical Power

AIRWORTHINESS DIRECTIVE (AD)
Not specified

SERVICE BULLETIN (SB)
Not specified

CHECK
Not specified

SHORT FAULT NAME
Citation hydraulic pressure loss

ERROR / FAULT INDICATIONS
Development scenario: Citation hydraulic pressure loss; aircraft is unavailable pending corrective action.

TROUBLESHOOTING STATUS
Troubleshooting Complete - All required Items listed

TSM/FIM REFERENCE
T330-006

ROLES AND RESPONSIBILITIES
Responding provider supplies qualified personnel, material trace, and completion records.

Citation hydraulic pressure loss affecting a Bombardier Learjet 60; Development test data requiring coordinated recovery support.

Items (2)

PARTS & ROTABLES - WANTED

Qty 1

Citation hydraulic pressure loss - replacement component 1

Item Id: TNQDQ

Traceable replacement material required for Citation hydraulic pressure loss.

PART / IPC REFERENCE
T330-AOG-BIZ-1-1

REQUIRED ONSITE
23SEP26 1446Z

AIRCRAFT MODEL
Bombardier Learjet 60

ENGINE MODEL
Not specified

ATA 100 CHAPTERS
20 Standard Practices - Airframe

CONDITION
Not specified

TRACE
Not specified

RELEASE DOCUMENTATION
Not specified

MAINTENANCE SERVICES - WANTED

Qty Not specified

Citation hydraulic pressure loss - support service 2

Item Id: VND7D

Qualified technical support required for Citation hydraulic pressure loss.

PART / IPC REFERENCE
Not specified

REQUIRED ONSITE
23SEP26 1446Z

AIRCRAFT MODEL
Bombardier Learjet 60

ENGINE MODEL
Not specified

ATA 100 CHAPTERS
24 Electrical Power

CONDITION
Not specified

TRACE
Not specified

RELEASE DOCUMENTATION
Not specified

Status Updates (0)

No visible Status Updates.