

ALERT: 26-NCNQ - CRITICAL AOG

WANTED

# Powerplant mechanic onsite, FAA A&P

Item Id: 4MG4M

Maintenance Services - Boeing 737-700 - KSAN

### Item Description

Provide an FAA A&P mechanic with CFM56-7B experience for number 2 engine fuel system troubleshooting, HMU and pump replacement, leak inspection, and return-to-service support.

| Item Details                  |                          |
|-------------------------------|--------------------------|
| PART / IPC REFERENCE          | ALTERNATE PART NUMBERS   |
| Not specified                 | Not specified            |
| QUANTITY                      | REQUIRED ONSITE          |
| Not specified                 | 29SEP26 1000Z            |
| REVISION                      | MANUFACTURER             |
| Not specified                 | Not specified            |
| MANUFACTURER TYPES            | ACCEPTABLE MANUFACTURERS |
| Not specified                 | Not specified            |
| AIRCRAFT MANUFACTURER         | AIRCRAFT MODEL           |
| Not specified                 | Boeing 737-700           |
| ENGINE MANUFACTURER           | ENGINE MODEL             |
| Not specified                 | CFM56-7B                 |
| ATA 100 CHAPTERS              | CONDITION                |
| 73 Engine Fuel and Control    | SV                       |
| TRACE                         | RELEASE DOCUMENTATION    |
| Not specified                 | Not specified            |
| TRANSACTION TYPES             | INCOTERM                 |
| Not specified                 | Not specified            |
| ONSITE LOCATION TYPE          | SERVICE AREA             |
| Hangar / Maintenance Facility | Not specified            |
| LEAD TIME                     | EXPORT READY             |
| Not specified                 | Not specified            |
| WARRANTY                      | WARRANTY TERMS           |
| Not specified                 | Not specified            |