ALERT: 26-NCNQ - CRITICAL AOG

WANTED

Powerplant mechanic onsite, FAA A&P

Item Id: 4MG4M

Maintenance Services - Boeing 737-700 - KSAN

Item Description

Provide an FAA A&P mechanic with CFM56-7B experience for number 2 engine fuel system troubleshooting, HMU and pump replacement, leak inspection, and return-to-service support.

Item Details

PART / IPC REFERENCE **Not specified**	ALTERNATE PART NUMBERS **Not specified**
QUANTITY **Not specified**	REQUIRED ONSITE **29SEP26 1000Z**
REVISION **Not specified**	MANUFACTURER **Not specified**
MANUFACTURER TYPES **Not specified**	ACCEPTABLE MANUFACTURERS **Not specified**
AIRCRAFT MANUFACTURER **Not specified**	AIRCRAFT MODEL **Boeing 737-700**
ENGINE MANUFACTURER **Not specified**	ENGINE MODEL **CFM56-7B**
ATA 100 CHAPTERS 73 Engine Fuel and Control	CONDITION **SV**
TRACE **Not specified**	RELEASE DOCUMENTATION **Not specified**
TRANSACTION TYPES **Not specified**	INCOTERM **Not specified**
ONSITE LOCATION TYPE **Hangar / Maintenance Facility**	SERVICE AREA **Not specified**
LEAD TIME **Not specified**	EXPORT READY **Not specified**
WARRANTY **Not specified**	WARRANTY TERMS **Not specified**