ALERT: 26-VTJY - CRITICAL AOG

WANTED

Core borescope inspection, CFM56-7B

Item Id: GQQVW

Maintenance Services - Boeing 737-800 - KBWI

Item Description

HPC and HPT borescope per AMM bird strike task, report with images

Item Details

PART / IPC REFERENCE **Not specified**	ALTERNATE PART NUMBERS **Not specified**
QUANTITY **Not specified**	REQUIRED ONSITE **25SEP26 1536Z**
REVISION **Not specified**	MANUFACTURER **Not specified**
MANUFACTURER TYPES **Not specified**	ACCEPTABLE MANUFACTURERS **Not specified**
AIRCRAFT MANUFACTURER **Not specified**	AIRCRAFT MODEL **Boeing 737-800**
ENGINE MANUFACTURER **Not specified**	ENGINE MODEL **CFM56-7B**
ATA 100 CHAPTERS 72 Engine	CONDITION **OH, SV**
TRACE **Not specified**	RELEASE DOCUMENTATION **Not specified**
TRANSACTION TYPES **Not specified**	INCOTERM **Not specified**
ONSITE LOCATION TYPE **Hangar / Maintenance Facility**	SERVICE AREA **Not specified**
LEAD TIME **Not specified**	EXPORT READY **Not specified**
WARRANTY **Not specified**	WARRANTY TERMS **Not specified**