

ALERT: 26-VTJY - CRITICAL AOG

WANTED

Core borescope inspection, CFM56-7B

Item Id: GQQVW

Maintenance Services - Boeing 737-800 - KBWI

Item Description

HPC and HPT borescope per AMM bird strike task, report with images

Item Details

PART / IPC REFERENCE	ALTERNATE PART NUMBERS
Not specified	Not specified
QUANTITY	REQUIRED ONSITE
Not specified	25SEP26 1536Z
REVISION	MANUFACTURER
Not specified	Not specified
MANUFACTURER TYPES	ACCEPTABLE MANUFACTURERS
Not specified	Not specified
AIRCRAFT MANUFACTURER	AIRCRAFT MODEL
Not specified	Boeing 737-800
ENGINE MANUFACTURER	ENGINE MODEL
Not specified	CFM56-7B
ATA 100 CHAPTERS	CONDITION
72 Engine	OH, SV
TRACE	RELEASE DOCUMENTATION
Not specified	Not specified
TRANSACTION TYPES	INCOTERM
Not specified	Not specified
ONSITE LOCATION TYPE	SERVICE AREA
Hangar / Maintenance Facility	Not specified
LEAD TIME	EXPORT READY
Not specified	Not specified
WARRANTY	WARRANTY TERMS
Not specified	Not specified