

ALERT: 26-FPVW - CRITICAL AOG

WANTED

Engine-driven hydraulic pump

Item Id: TXWFC

Parts & Rotables - Bombardier Challenger 350 / 3500 - KVNY

Item Description

Engine-driven hydraulic pump assembly, inspected and serviceable with traceability for Challenger 350.

Item Details

PART / IPC REFERENCE	ALTERNATE PART NUMBERS
CH35-29-PMP-101	Not specified
QUANTITY	REQUIRED ONSITE
1	23SEP26 1715Z
REVISION	MANUFACTURER
Rev A	Not specified
MANUFACTURER TYPES	ACCEPTABLE MANUFACTURERS
Not specified	Bombardier / Parker
AIRCRAFT MANUFACTURER	AIRCRAFT MODEL
Not specified	Bombardier Challenger 350 / 3500
ENGINE MANUFACTURER	ENGINE MODEL
Not specified	HTF7350
ATA 100 CHAPTERS	CONDITION
29 Hydraulic Power	OH, SV
TRACE	RELEASE DOCUMENTATION
OEM trace	FAA Form 8130-3
TRANSACTION TYPES	INCOTERM
Outright Purchase	DAP
ONSITE LOCATION TYPE	SERVICE AREA
Ramp	Not specified
LEAD TIME	EXPORT READY
Not specified	Not specified
WARRANTY	WARRANTY TERMS
No	Not specified