

ALERT: 26-FPVW - CRITICAL AOG

WANTED

Hydraulic leak isolation & ground run support

Item Id: 3RMKK
Maintenance Services - Bombardier Challenger 350 / 3500 - KVMY

Item Description

Onsite hydraulic leak isolation, component assessment, servicing, and controlled ground run support with documented findings.

Item Details

PART / IPC REFERENCE	ALTERNATE PART NUMBERS
Not specified	Not specified
QUANTITY	REQUIRED ONSITE
Not specified	23SEP26 1715Z
REVISION	MANUFACTURER
Not specified	Not specified
MANUFACTURER TYPES	ACCEPTABLE MANUFACTURERS
Not specified	Not specified
AIRCRAFT MANUFACTURER	AIRCRAFT MODEL
Not specified	Bombardier Challenger 350 / 3500
ENGINE MANUFACTURER	ENGINE MODEL
Not specified	HTF7350
ATA 100 CHAPTERS	CONDITION
29 Hydraulic Power	OH, SV
TRACE	RELEASE DOCUMENTATION
Not specified	Not specified
TRANSACTION TYPES	INCOTERM
Not specified	Not specified
ONSITE LOCATION TYPE	SERVICE AREA
Ramp	Not specified
LEAD TIME	EXPORT READY
Not specified	Not specified
WARRANTY	WARRANTY TERMS
Not specified	Not specified