ALERT: 26-NWCX - CRITICAL AOG

WANTED

Hydraulic pump assembly

Item Id: PFACM

Parts & Rotables - Boeing 737-800 - KATL

Item Description

Overhauled hydraulic pump assembly suitable for 737NG installation.

Item Details

PART / IPC REFERENCE 887B1001-01	ALTERNATE PART NUMBERS Not specified
QUANTITY 1	REQUIRED ONSITE 17SEP26 1450Z
REVISION Not specified	MANUFACTURER Approved aviation supplier
MANUFACTURER TYPES Not specified	ACCEPTABLE MANUFACTURERS OEM or approved equivalent
AIRCRAFT MANUFACTURER Not specified	AIRCRAFT MODEL Boeing 737-800
ENGINE MANUFACTURER Not specified	ENGINE MODEL CFM56-7B
ATA 100 CHAPTERS Not specified	CONDITION Not specified
TRACE Not specified	RELEASE DOCUMENTATION Not specified
TRANSACTION TYPES Not specified	INCOTERM Not specified
ONSITE LOCATION TYPE Ramp	SERVICE AREA Not specified
LEAD TIME Not specified	EXPORT READY Yes
WARRANTY No	WARRANTY TERMS Not specified