

ALERT: 26-NWCX - CRITICAL AOG

WANTED

Hydraulic pump assembly

Item Id: PFACM
Parts & Rotables - Boeing 737-800 - KATL

Item Description Overhauled hydraulic pump assembly suitable for 737NG installation.	
Item Details	
PART / IPC REFERENCE	ALTERNATE PART NUMBERS
887B1001-01	Not specified
QUANTITY	REQUIRED ONSITE
1	17SEP26 1450Z
REVISION	MANUFACTURER
Not specified	Approved aviation supplier
MANUFACTURER TYPES	ACCEPTABLE MANUFACTURERS
Not specified	OEM or approved equivalent
AIRCRAFT MANUFACTURER	AIRCRAFT MODEL
Not specified	Boeing 737-800
ENGINE MANUFACTURER	ENGINE MODEL
Not specified	CFM56-7B
ATA 100 CHAPTERS	CONDITION
Not specified	Not specified
TRACE	RELEASE DOCUMENTATION
Not specified	Not specified
TRANSACTION TYPES	INCOTERM
Not specified	Not specified
ONSITE LOCATION TYPE	SERVICE AREA
Ramp	Not specified
LEAD TIME	EXPORT READY
Not specified	Yes
WARRANTY	WARRANTY TERMS
No	Not specified