

ALERT: 26-ANRU - CRITICAL AOG

Falcon 7X thrust reverser disagree - KLAS

Dassault Aviation Falcon 7X - PW307

Public Alert Information

STATUS

active

PRIORITY

CRITICAL

ICAO LOCATION

KLAS

AIRCRAFT SERIES

Not specified

IMPACT TYPE

Charter

RTS TARGET

24SEP26 1733Z

ATA 100 CHAPTERS

78

Exhaust

SERVICE BULLETIN (SB)

Not specified

SHORT FAULT NAME

Thrust reverser disagree

TROUBLESHOOTING STATUS

Troubleshooting Incomplete - Additional Items may be required

ROLES AND RESPONSIBILITIES

Client coordinates aircraft access and records; qualified FAA A&P supplier performs troubleshooting, rigging, and operational testing; supplier provides service documentation and return-to-service records.

ALERT TYPE

AOG Alert

ADDED TO PLATFORM

22SEP26 1749Z

AIRCRAFT MODEL

Dassault Aviation Falcon 7X

ENGINE MODEL

PW307

MX WINDOW OPENS

22SEP26 1747Z

ALERT SPECIFICS

Unscheduled Maintenance

AIRWORTHINESS DIRECTIVE (AD)

Not specified

CHECK

Not specified

ERROR / FAULT INDICATIONS

Thrust reverser unlock / disagree CAS indication during landing rollout; system not available.

TSM/FIM REFERENCE

Not specified

Business jet held at Las Vegas for thrust reverser unlock and disagree CAS indication. Unscheduled exhaust system maintenance response requested on the FBO ramp.

Page 1 of 3

Items (5)

PARTS & ROTABLES - WANTED

Qty 1

Thrust reverser actuator

Item Id: EG4HR

Thrust reverser actuator, inspected and serviceable for Falcon 7X.

PART / IPC REFERENCE	REQUIRED ONSITE
F7X-78-ACT-102	24SEP26 1733Z
AIRCRAFT MODEL	ENGINE MODEL
Not specified	Not specified
ATA 100 CHAPTERS	CONDITION
78 Exhaust	SV
TRACE	RELEASE DOCUMENTATION
OEM trace	FAA Form 8130-3

MAINTENANCE SERVICES - WANTED

Qty Not specified

Flexible hydraulic hose for TR

Item Id: NPGQJ

Inspect flexible thrust reverser hydraulic hose, replace as required, and perform pressure and leak checks on Falcon 7X.

PART / IPC REFERENCE	REQUIRED ONSITE
Not specified	24SEP26 1733Z
AIRCRAFT MODEL	ENGINE MODEL
Not specified	Not specified
ATA 100 CHAPTERS	CONDITION
78 Exhaust	SV
TRACE	RELEASE DOCUMENTATION
Not specified	Not specified

PARTS & ROTABLES - WANTED

Qty 1

TR control unit / proximity sensor

Item Id: FRWCH

Thrust reverser control unit and proximity sensor assembly, inspected and serviceable for Falcon 7X.

PART / IPC REFERENCE	REQUIRED ONSITE
F7X-78-TRCU-204	24SEP26 1733Z
AIRCRAFT MODEL	ENGINE MODEL
Not specified	Not specified
ATA 100 CHAPTERS	CONDITION
78 Exhaust	SV
TRACE	RELEASE DOCUMENTATION
OEM trace	FAA Form 8130-3

MAINTENANCE SERVICES - WANTED

Qty Not specified

TR rigging check and operational test

Item Id: CKH34

Perform thrust reverser rigging check, actuator and proximity indication verification, hydraulic leak check, and operational test.

PART / IPC REFERENCE	REQUIRED ONSITE
Not specified	24SEP26 1733Z
AIRCRAFT MODEL	ENGINE MODEL
Not specified	Not specified
ATA 100 CHAPTERS	CONDITION
78 Exhaust	SV
TRACE	RELEASE DOCUMENTATION
Not specified	Not specified

MAINTENANCE SERVICES - WANTED

Qty Not specified

Hydraulic isolation valve for TR

Item Id: C33UV

Inspect thrust reverser hydraulic isolation valve, verify operation, and support replacement and leak check on Falcon 7X.

PART / IPC REFERENCE	REQUIRED ONSITE
Not specified	24SEP26 1733Z
AIRCRAFT MODEL	ENGINE MODEL
Not specified	Not specified
ATA 100 CHAPTERS	CONDITION
78 Exhaust	SV
TRACE	RELEASE DOCUMENTATION
Not specified	Not specified

Status Updates (0)

No visible Status Updates.