ALERT: 26-ANRU - CRITICAL AOG

Falcon 7X thrust reverser disagree - KLAS

Dassault Aviation Falcon 7X - PW307

Public Alert Information

STATUS
active

ALERT TYPE
AOG Alert

PRIORITY
CRITICAL

ADDED TO PLATFORM
22SEP26 1749Z

ICAO LOCATION
KLAS

AIRCRAFT MODEL
Dassault Aviation Falcon 7X

AIRCRAFT SERIES
Not specified

ENGINE MODEL
PW307

IMPACT TYPE
Charter

MX WINDOW OPENS
22SEP26 1747Z

RTS TARGET
24SEP26 1733Z

ALERT SPECIFICS
Unscheduled Maintenance

ATA 100 CHAPTERS
78 Exhaust

AIRWORTHINESS DIRECTIVE (AD)
Not specified

SERVICE BULLETIN (SB)
Not specified

CHECK
Not specified

SHORT FAULT NAME
Thrust reverser disagree

ERROR / FAULT INDICATIONS
Thrust reverser unlock / disagree CAS indication during landing rollout; system not available.

TROUBLESHOOTING STATUS
Troubleshooting Incomplete - Additional Items may be required

TSM/FIM REFERENCE
Not specified

ROLES AND RESPONSIBILITIES
Client coordinates aircraft access and records; qualified FAA A&P supplier performs troubleshooting, rigging, and operational testing; supplier provides service documentation and return-to-service records.

Business jet held at Las Vegas for thrust reverser unlock and disagree CAS indication. Unscheduled exhaust system maintenance response requested on the FBO ramp.

Items (5)

PARTS & ROTABLES - WANTED

Qty 1

Thrust reverser actuator

Item Id: EG4HR

Thrust reverser actuator, inspected and serviceable for Falcon 7X.

PART / IPC REFERENCE **F7X-78-ACT-102**	REQUIRED ONSITE **24SEP26 1733Z**
AIRCRAFT MODEL **Not specified**	ENGINE MODEL **Not specified**
ATA 100 CHAPTERS 78 Exhaust	CONDITION **SV**
TRACE **OEM trace**	RELEASE DOCUMENTATION **FAA Form 8130-3**

MAINTENANCE SERVICES - WANTED

Qty Not specified

Flexible hydraulic hose for TR

Item Id: NPGQJ

Inspect flexible thrust reverser hydraulic hose, replace as required, and perform pressure and leak checks on Falcon 7X.

PART / IPC REFERENCE **Not specified**	REQUIRED ONSITE **24SEP26 1733Z**
AIRCRAFT MODEL **Not specified**	ENGINE MODEL **Not specified**
ATA 100 CHAPTERS 78 Exhaust	CONDITION **SV**
TRACE **Not specified**	RELEASE DOCUMENTATION **Not specified**

PARTS & ROTABLES - WANTED

Qty 1

TR control unit / proximity sensor

Item Id: FRWCH

Thrust reverser control unit and proximity sensor assembly, inspected and serviceable for Falcon 7X.

PART / IPC REFERENCE **F7X-78-TRCU-204**	REQUIRED ONSITE **24SEP26 1733Z**
AIRCRAFT MODEL **Not specified**	ENGINE MODEL **Not specified**
ATA 100 CHAPTERS 78 Exhaust	CONDITION **SV**
TRACE **OEM trace**	RELEASE DOCUMENTATION **FAA Form 8130-3**

MAINTENANCE SERVICES - WANTED

Qty Not specified

TR rigging check and operational test

Item Id: CKH34

Perform thrust reverser rigging check, actuator and proximity indication verification, hydraulic leak check, and operational test.

PART / IPC REFERENCE
Not specified

REQUIRED ONSITE
24SEP26 1733Z

AIRCRAFT MODEL
Not specified

ENGINE MODEL
Not specified

ATA 100 CHAPTERS
78 Exhaust

CONDITION
SV

TRACE
Not specified

RELEASE DOCUMENTATION
Not specified

MAINTENANCE SERVICES - WANTED

Qty Not specified

Hydraulic isolation valve for TR

Item Id: C33UV

Inspect thrust reverser hydraulic isolation valve, verify operation, and support replacement and leak check on Falcon 7X.

PART / IPC REFERENCE
Not specified

REQUIRED ONSITE
24SEP26 1733Z

AIRCRAFT MODEL
Not specified

ENGINE MODEL
Not specified

ATA 100 CHAPTERS
78 Exhaust

CONDITION
SV

TRACE
Not specified

RELEASE DOCUMENTATION
Not specified

Status Updates (0)

No visible Status Updates.