ALERT: 26-9AQR - CRITICAL AOG

WANTED

Hawker windshield heat failure - support service 4

Item Id: AEQ3G

Logistics & Customs - Bombardier Challenger 300 / 350 - KATL

Item Description

Qualified technical support required for Hawker windshield heat failure.

Item Details

PART / IPC REFERENCE **Not specified**	ALTERNATE PART NUMBERS **Not specified**
QUANTITY **Not specified**	REQUIRED ONSITE **25SEP26 1446Z**
REVISION **Not specified**	MANUFACTURER **Not specified**
MANUFACTURER TYPES **Not specified**	ACCEPTABLE MANUFACTURERS **Not specified**
AIRCRAFT MANUFACTURER **Not specified**	AIRCRAFT MODEL **Bombardier Challenger 300 / 350**
ENGINE MANUFACTURER **Not specified**	ENGINE MODEL **PW600**
ATA 100 CHAPTERS 20 Standard Practices - Airframe	CONDITION **Not specified**
TRACE **Not specified**	RELEASE DOCUMENTATION **Not specified**
TRANSACTION TYPES **Not specified**	INCOTERM **Not specified**
ONSITE LOCATION TYPE **Hangar / Maintenance Facility**	SERVICE AREA **Not specified**
LEAD TIME **Not specified**	EXPORT READY **Not specified**
WARRANTY **Not specified**	WARRANTY TERMS **Not specified**