

ALERT: 26-9AQR - CRITICAL AOG

WANTED

Hawker windshield heat failure - replacement component 1

Item Id: EUPCN

Parts & Rotables - Bombardier Challenger 300 / 350 - KATL

Item Description

Traceable replacement material required for Hawker windshield heat failure.

Item Details

PART / IPC REFERENCE	ALTERNATE PART NUMBERS
T330-AOG-BIZ-3-1	Not specified
QUANTITY	REQUIRED ONSITE
1	25SEP26 1446Z
REVISION	MANUFACTURER
Not specified	Not specified
MANUFACTURER TYPES	ACCEPTABLE MANUFACTURERS
Not specified	Not specified
AIRCRAFT MANUFACTURER	AIRCRAFT MODEL
Not specified	Bombardier Challenger 300 / 350
ENGINE MANUFACTURER	ENGINE MODEL
Not specified	PW600
ATA 100 CHAPTERS	CONDITION
24 Electrical Power	Not specified
TRACE	RELEASE DOCUMENTATION
Not specified	Not specified
TRANSACTION TYPES	INCOTERM
Not specified	Not specified
ONSITE LOCATION TYPE	SERVICE AREA
Hangar / Maintenance Facility	Not specified
LEAD TIME	EXPORT READY
Not specified	Not specified
WARRANTY	WARRANTY TERMS
Not specified	Not specified