ALERT: 26-K994 - CRITICAL AOG

WANTED

Powerplant engineer onsite, EASA Part-66 B1

Item Id: JYGEQ

Maintenance Services - Boeing 737-800 - LEBL

Item Description

Provide an EASA B1 licensed engineer with CFM56-7B experience for fan blade replacement, trim balance if required, engine run, and certificate of release to service.

Item Details

PART / IPC REFERENCE
Not specified

ALTERNATE PART NUMBERS
Not specified

QUANTITY
Not specified

REQUIRED ONSITE
30SEP26 0600Z

REVISION
Not specified

MANUFACTURER
Not specified

MANUFACTURER TYPES
Not specified

ACCEPTABLE MANUFACTURERS
Not specified

AIRCRAFT MANUFACTURER
Not specified

AIRCRAFT MODEL
Boeing 737-800

ENGINE MANUFACTURER
Not specified

ENGINE MODEL
CFM56-7B

ATA 100 CHAPTERS
72 Engine

CONDITION
SV

TRACE
Not specified

RELEASE DOCUMENTATION
Not specified

TRANSACTION TYPES
Not specified

INCOTERM
Not specified

ONSITE LOCATION TYPE
Ramp

SERVICE AREA
Not specified

LEAD TIME
Not specified

EXPORT READY
Not specified

WARRANTY
Not specified

WARRANTY TERMS
Not specified