ALERT: 26-K994 - CRITICAL AOG

WANTED

Fan blade shim and retainer kit

Item Id: WQVDM

Parts & Rotables - Boeing 737-800 - LEBL

Item Description

New fan blade shims, retainers, and dry film lubricant consumables for CFM56-7B fan blade replacement.

Item Details

PART / IPC REFERENCE **CFM56-7B-72-FBK**	ALTERNATE PART NUMBERS **340-043-601-0**
QUANTITY **1**	REQUIRED ONSITE **30SEP26 0600Z**
REVISION **Rev 2**	MANUFACTURER **Not specified**
MANUFACTURER TYPES **Not specified**	ACCEPTABLE MANUFACTURERS **CFM International**
AIRCRAFT MANUFACTURER **Not specified**	AIRCRAFT MODEL **Boeing 737-800**
ENGINE MANUFACTURER **Not specified**	ENGINE MODEL **CFM56-7B**
ATA 100 CHAPTERS 72 Engine	CONDITION **NE**
TRACE **OEM trace**	RELEASE DOCUMENTATION **EASA Form 1, Certificate of Conformance**
TRANSACTION TYPES **Outright Purchase**	INCOTERM **DAP**
ONSITE LOCATION TYPE **Ramp**	SERVICE AREA **Not specified**
LEAD TIME **Not specified**	EXPORT READY **Not specified**
WARRANTY **No**	WARRANTY TERMS **Not specified**