

ALERT: 26-K994 - CRITICAL AOG

WANTED

Fan blade shim and retainer kit

Item Id: WQVDM

Parts & Rotables - Boeing 737-800 - LEBL

Item Description

New fan blade shims, retainers, and dry film lubricant consumables for CFM56-7B fan blade replacement.

Item Details	
PART / IPC REFERENCE	ALTERNATE PART NUMBERS
CFM56-7B-72-FBK	340-043-601-0
QUANTITY	REQUIRED ONSITE
1	30SEP26 0600Z
REVISION	MANUFACTURER
Rev 2	Not specified
MANUFACTURER TYPES	ACCEPTABLE MANUFACTURERS
Not specified	CFM International
AIRCRAFT MANUFACTURER	AIRCRAFT MODEL
Not specified	Boeing 737-800
ENGINE MANUFACTURER	ENGINE MODEL
Not specified	CFM56-7B
ATA 100 CHAPTERS	CONDITION
72 Engine	NE
TRACE	RELEASE DOCUMENTATION
OEM trace	EASA Form 1, Certificate of Conformance
TRANSACTION TYPES	INCOTERM
Outright Purchase	DAP
ONSITE LOCATION TYPE	SERVICE AREA
Ramp	Not specified
LEAD TIME	EXPORT READY
Not specified	Not specified
WARRANTY	WARRANTY TERMS
No	Not specified