

ALERT: 26-Q9XW - CRITICAL AOG

WANTED

Bell 206 fuel-control fault - support service 2

Item Id: RWN3K

Maintenance Services - Airbus Helicopters H125 / AS350 Écureuil - KATL

Item Description

Qualified technical support required for Bell 206 fuel-control fault.

Item Details

PART / IPC REFERENCE	ALTERNATE PART NUMBERS
Not specified	Not specified
QUANTITY	REQUIRED ONSITE
Not specified	28SEP26 1446Z
REVISION	MANUFACTURER
Not specified	Not specified
MANUFACTURER TYPES	ACCEPTABLE MANUFACTURERS
Not specified	Not specified
AIRCRAFT MANUFACTURER	AIRCRAFT MODEL
Not specified	Airbus Helicopters H125 / AS350 Écureuil
ENGINE MANUFACTURER	ENGINE MODEL
Not specified	Allison 250-C20/C30
ATA 100 CHAPTERS	CONDITION
5 - Time Limits / Maintenance Checks	Not specified
TRACE	RELEASE DOCUMENTATION
Not specified	Not specified
TRANSACTION TYPES	INCOTERM
Not specified	Not specified
ONSITE LOCATION TYPE	SERVICE AREA
Hangar / Maintenance Facility	Not specified
LEAD TIME	EXPORT READY
Not specified	Not specified
WARRANTY	WARRANTY TERMS
Not specified	Not specified