

ALERT: 26-Q9XW - CRITICAL AOG

Bell 206 fuel-control fault

Airbus Helicopters H125 / AS350 Écureuil - Allison 250-C20/C30

Public Alert Information	
STATUS active	ALERT TYPE AOG Alert
PRIORITY CRITICAL	ADDED TO PLATFORM 16SEP26 1445Z
ICAO LOCATION KATL	AIRCRAFT MODEL Airbus Helicopters H125 / AS350 Écureuil
AIRCRAFT SERIES H125 / AS350 Écureuil	ENGINE MODEL Allison 250-C20/C30
IMPACT TYPE Charter	MX WINDOW OPENS 28SEP26 1445Z
RTS TARGET 29SEP26 1445Z	ALERT SPECIFICS Unscheduled Maintenance
ATA 100 CHAPTERS 5 - Time Limits / Maintenance Checks 13 Special Inspections 24 Electrical Power	AIRWORTHINESS DIRECTIVE (AD) Not specified
SERVICE BULLETIN (SB) Not specified	CHECK Not specified
SHORT FAULT NAME Bell 206 fuel-control fault	ERROR / FAULT INDICATIONS Development scenario: Bell 206 fuel-control fault; aircraft is unavailable pending corrective action.
TROUBLESHOOTING STATUS Troubleshooting Complete - All required Items listed	TSM/FIM REFERENCE T330-011
ROLES AND RESPONSIBILITIES Responding provider supplies qualified personnel, material trace, and completion records.	
Bell 206 fuel-control fault affecting a Airbus Helicopters H125 / AS350 Écureuil; Development test data requiring coordinated recovery support.	

Items (3)

PARTS & ROTABLES - WANTED

Qty 1

Bell 206 fuel-control fault - replacement component 1

Item Id: TCPHF

Traceable replacement material required for Bell 206 fuel-control fault.

PART / IPC REFERENCE	REQUIRED ONSITE
T330-AOG-ROT-2-1	28SEP26 1446Z
AIRCRAFT MODEL	ENGINE MODEL
Airbus Helicopters H125 / AS350 Écureuil	Not specified
ATA 100 CHAPTERS	CONDITION
24 Electrical Power	Not specified
TRACE	RELEASE DOCUMENTATION
Not specified	Not specified

TESTING & CERTIFICATION - WANTED

Qty Not specified

Bell 206 fuel-control fault - support service 3

Item Id: 9R3TK

Qualified technical support required for Bell 206 fuel-control fault.

PART / IPC REFERENCE	REQUIRED ONSITE
Not specified	28SEP26 1446Z
AIRCRAFT MODEL	ENGINE MODEL
Airbus Helicopters H125 / AS350 Écureuil	Not specified
ATA 100 CHAPTERS	CONDITION
13 Special Inspections	Not specified
TRACE	RELEASE DOCUMENTATION
Not specified	Not specified

MAINTENANCE SERVICES - WANTED

Qty Not specified

Bell 206 fuel-control fault - support service 2

Item Id: RWN3K

Qualified technical support required for Bell 206 fuel-control fault.

PART / IPC REFERENCE	REQUIRED ONSITE
Not specified	28SEP26 1446Z
AIRCRAFT MODEL	ENGINE MODEL
Airbus Helicopters H125 / AS350 Écureuil	Not specified
ATA 100 CHAPTERS	CONDITION
5 - Time Limits / Maintenance Checks	Not specified
TRACE	RELEASE DOCUMENTATION
Not specified	Not specified

Status Updates (0)

No visible Status Updates.