ALERT: 26-Q9XW - CRITICAL AOG

Bell 206 fuel-control fault

Airbus Helicopters H125 / AS350 Écureuil - Allison 250-C20/C30

Public Alert Information

STATUS
active

ALERT TYPE
AOG Alert

PRIORITY
CRITICAL

ADDED TO PLATFORM
16SEP26 1445Z

ICAO LOCATION
KATL

AIRCRAFT MODEL
Airbus Helicopters H125 / AS350 Écureuil

AIRCRAFT SERIES
H125 / AS350 Écureuil

ENGINE MODEL
Allison 250-C20/C30

IMPACT TYPE
Charter

MX WINDOW OPENS
28SEP26 1445Z

RTS TARGET
29SEP26 1445Z

ALERT SPECIFICS
Unscheduled Maintenance

ATA 100 CHAPTERS
5 - Time Limits / Maintenance Checks
13 Special Inspections
24 Electrical Power

AIRWORTHINESS DIRECTIVE (AD)
Not specified

SERVICE BULLETIN (SB)
Not specified

CHECK
Not specified

SHORT FAULT NAME
Bell 206 fuel-control fault

ERROR / FAULT INDICATIONS
Development scenario: Bell 206 fuel-control fault; aircraft is unavailable pending corrective action.

TROUBLESHOOTING STATUS
Troubleshooting Complete - All required Items listed

TSM/FIM REFERENCE
T330-011

ROLES AND RESPONSIBILITIES
Responding provider supplies qualified personnel, material trace, and completion records.

Bell 206 fuel-control fault affecting a Airbus Helicopters H125 / AS350 Écureuil; Development test data requiring coordinated recovery support.

Items (3)

PARTS & ROTABLES - WANTED

Qty 1

Bell 206 fuel-control fault - replacement component 1

Item Id: TCPHF

Traceable replacement material required for Bell 206 fuel-control fault.

PART / IPC REFERENCE
T330-AOG-ROT-2-1

REQUIRED ONSITE
28SEP26 1446Z

AIRCRAFT MODEL
Airbus Helicopters H125 / AS350 Écureuil

ENGINE MODEL
Not specified

ATA 100 CHAPTERS
24 Electrical Power

CONDITION
Not specified

TRACE
Not specified

RELEASE DOCUMENTATION
Not specified

TESTING & CERTIFICATION - WANTED

Qty Not specified

Bell 206 fuel-control fault - support service 3

Item Id: 9R3TK

Qualified technical support required for Bell 206 fuel-control fault.

PART / IPC REFERENCE
Not specified

REQUIRED ONSITE
28SEP26 1446Z

AIRCRAFT MODEL
Airbus Helicopters H125 / AS350 Écureuil

ENGINE MODEL
Not specified

ATA 100 CHAPTERS
13 Special Inspections

CONDITION
Not specified

TRACE
Not specified

RELEASE DOCUMENTATION
Not specified

MAINTENANCE SERVICES - WANTED

Qty Not specified

Bell 206 fuel-control fault - support service 2

Item Id: RWN3K

Qualified technical support required for Bell 206 fuel-control fault.

PART / IPC REFERENCE
Not specified

REQUIRED ONSITE
28SEP26 1446Z

AIRCRAFT MODEL
Airbus Helicopters H125 / AS350 Écureuil

ENGINE MODEL
Not specified

ATA 100 CHAPTERS
5 - Time Limits / Maintenance Checks

CONDITION
Not specified

TRACE
Not specified

RELEASE DOCUMENTATION
Not specified

Status Updates (0)

No visible Status Updates.