

ALERT: 26-WKAH - CRITICAL AOG

WANTED

H125 rotor vibration - replacement component 1

Item Id: CKMUF

Parts & Rotables - Airbus Helicopters H120 / EC120 Colibri - KATL

Item Description

Traceable replacement material required for H125 rotor vibration.

Item Details

PART / IPC REFERENCE	ALTERNATE PART NUMBERS
T330-AOG-ROT-1-1	Not specified
QUANTITY	REQUIRED ONSITE
1	27SEP26 1446Z
REVISION	MANUFACTURER
Not specified	Not specified
MANUFACTURER TYPES	ACCEPTABLE MANUFACTURERS
Not specified	Not specified
AIRCRAFT MANUFACTURER	AIRCRAFT MODEL
Not specified	Airbus Helicopters H120 / EC120 Colibri
ENGINE MANUFACTURER	ENGINE MODEL
Not specified	Allison 250-C20/C30
ATA 100 CHAPTERS	CONDITION
13 Special Inspections	Not specified
TRACE	RELEASE DOCUMENTATION
Not specified	Not specified
TRANSACTION TYPES	INCOTERM
Not specified	Not specified
ONSITE LOCATION TYPE	SERVICE AREA
Hangar / Maintenance Facility	Not specified
LEAD TIME	EXPORT READY
Not specified	Not specified
WARRANTY	WARRANTY TERMS
Not specified	Not specified