ALERT: 26-A3MW - CRITICAL AOG

Learjet starter-generator failure

Bombardier Learjet 70 / 75 - PW600

Public Alert Information

STATUS
active

ALERT TYPE
AOG Alert

PRIORITY
CRITICAL

ADDED TO PLATFORM
16SEP26 1445Z

ICAO LOCATION
KATL

AIRCRAFT MODEL
Bombardier Learjet 70 / 75

AIRCRAFT SERIES
Learjet 70 / 75

ENGINE MODEL
PW600

IMPACT TYPE
Charter

MX WINDOW OPENS
24SEP26 1445Z

RTS TARGET
25SEP26 1445Z

ALERT SPECIFICS
Unscheduled Maintenance

ATA 100 CHAPTERS
5 - Time Limits / Maintenance Checks
13 Special Inspections
20 Standard Practices - Airframe

AIRWORTHINESS DIRECTIVE (AD)
Not specified

SERVICE BULLETIN (SB)
Not specified

CHECK
Not specified

SHORT FAULT NAME
Learjet starter-generator failure

ERROR / FAULT INDICATIONS
Development scenario: Learjet starter-generator failure; aircraft is unavailable pending corrective action.

TROUBLESHOOTING STATUS
Troubleshooting Complete - All required Items listed

TSM/FIM REFERENCE
T330-007

ROLES AND RESPONSIBILITIES
Responding provider supplies qualified personnel, material trace, and completion records.

Learjet starter-generator failure affecting a Bombardier Learjet 70 / 75; Development test data requiring coordinated recovery support.

Items (3)

TESTING & CERTIFICATION - WANTED

Qty Not specified

Learjet starter-generator failure - support service 3

Item Id: CWK7G

Qualified technical support required for Learjet starter-generator failure.

PART / IPC REFERENCE
Not specified

REQUIRED ONSITE
24SEP26 1446Z

AIRCRAFT MODEL
Bombardier Learjet 70 / 75

ENGINE MODEL
Not specified

ATA 100 CHAPTERS
20 Standard Practices - Airframe

CONDITION
Not specified

TRACE
Not specified

RELEASE DOCUMENTATION
Not specified

PARTS & ROTABLES - WANTED

Qty 1

Learjet starter-generator failure - replacement component 1

Item Id: W4CXD

Traceable replacement material required for Learjet starter-generator failure.

PART / IPC REFERENCE
T330-AOG-BIZ-2-1

REQUIRED ONSITE
24SEP26 1446Z

AIRCRAFT MODEL
Bombardier Learjet 70 / 75

ENGINE MODEL
Not specified

ATA 100 CHAPTERS
5 - Time Limits / Maintenance Checks

CONDITION
Not specified

TRACE
Not specified

RELEASE DOCUMENTATION
Not specified

MAINTENANCE SERVICES - WANTED

Qty Not specified

Learjet starter-generator failure - support service 2

Item Id: YTGFT

Qualified technical support required for Learjet starter-generator failure.

PART / IPC REFERENCE
Not specified

REQUIRED ONSITE
24SEP26 1446Z

AIRCRAFT MODEL
Bombardier Learjet 70 / 75

ENGINE MODEL
Not specified

ATA 100 CHAPTERS
13 Special Inspections

CONDITION
Not specified

TRACE
Not specified

RELEASE DOCUMENTATION
Not specified

Status Updates (0)

No visible Status Updates.