

ALERT: 26-A3MW - CRITICAL AOG

Learjet starter-generator failure

Bombardier Learjet 70 / 75 - PW600

Public Alert Information	
STATUS active	ALERT TYPE AOG Alert
PRIORITY CRITICAL	ADDED TO PLATFORM 16SEP26 1445Z
ICAO LOCATION KATL	AIRCRAFT MODEL Bombardier Learjet 70 / 75
AIRCRAFT SERIES Learjet 70 / 75	ENGINE MODEL PW600
IMPACT TYPE Charter	MX WINDOW OPENS 24SEP26 1445Z
RTS TARGET 25SEP26 1445Z	ALERT SPECIFICS Unscheduled Maintenance
ATA 100 CHAPTERS 5 - Time Limits / Maintenance Checks 13 Special Inspections 20 Standard Practices - Airframe	AIRWORTHINESS DIRECTIVE (AD) Not specified
SERVICE BULLETIN (SB) Not specified	CHECK Not specified
SHORT FAULT NAME Learjet starter-generator failure	ERROR / FAULT INDICATIONS Development scenario: Learjet starter-generator failure; aircraft is unavailable pending corrective action.
TROUBLESHOOTING STATUS Troubleshooting Complete - All required Items listed	TSM/FIM REFERENCE T330-007
ROLES AND RESPONSIBILITIES Responding provider supplies qualified personnel, material trace, and completion records.	
Learjet starter-generator failure affecting a Bombardier Learjet 70 / 75; Development test data requiring coordinated recovery support.	

Items (3)

TESTING & CERTIFICATION - WANTED

Qty Not specified

Learjet starter-generator failure - support service 3

Item Id: CWK7G

Qualified technical support required for Learjet starter-generator failure.

PART / IPC REFERENCE	REQUIRED ONSITE
Not specified	24SEP26 1446Z
AIRCRAFT MODEL	ENGINE MODEL
Bombardier Learjet 70 / 75	Not specified
ATA 100 CHAPTERS	CONDITION
20 Standard Practices - Airframe	Not specified
TRACE	RELEASE DOCUMENTATION
Not specified	Not specified

PARTS & ROTABLES - WANTED

Qty 1

Learjet starter-generator failure - replacement component 1

Item Id: W4CXD

Traceable replacement material required for Learjet starter-generator failure.

PART / IPC REFERENCE	REQUIRED ONSITE
T330-AOG-BIZ-2-1	24SEP26 1446Z
AIRCRAFT MODEL	ENGINE MODEL
Bombardier Learjet 70 / 75	Not specified
ATA 100 CHAPTERS	CONDITION
5 - Time Limits / Maintenance Checks	Not specified
TRACE	RELEASE DOCUMENTATION
Not specified	Not specified

MAINTENANCE SERVICES - WANTED

Qty Not specified

Learjet starter-generator failure - support service 2

Item Id: YTGFT

Qualified technical support required for Learjet starter-generator failure.

PART / IPC REFERENCE	REQUIRED ONSITE
Not specified	24SEP26 1446Z
AIRCRAFT MODEL	ENGINE MODEL
Bombardier Learjet 70 / 75	Not specified
ATA 100 CHAPTERS	CONDITION
13 Special Inspections	Not specified
TRACE	RELEASE DOCUMENTATION
Not specified	Not specified

Status Updates (0)

No visible Status Updates.