

ALERT: 26-H3TG - CRITICAL AOG

WANTED

Challenger brake control fault - replacement component 1

Item Id: T9ECT

Parts & Rotables - Bombardier Challenger 350 / 3500 - KATL

Item Description

Traceable replacement material required for Challenger brake control fault.

Item Details

PART / IPC REFERENCE	ALTERNATE PART NUMBERS
T330-AOG-BIZ-4-1	Not specified
QUANTITY	REQUIRED ONSITE
1	26SEP26 1446Z
REVISION	MANUFACTURER
Not specified	Not specified
MANUFACTURER TYPES	ACCEPTABLE MANUFACTURERS
Not specified	Not specified
AIRCRAFT MANUFACTURER	AIRCRAFT MODEL
Not specified	Bombardier Challenger 350 / 3500
ENGINE MANUFACTURER	ENGINE MODEL
Not specified	PW600
ATA 100 CHAPTERS	CONDITION
24 Electrical Power	Not specified
TRACE	RELEASE DOCUMENTATION
Not specified	Not specified
TRANSACTION TYPES	INCOTERM
Not specified	Not specified
ONSITE LOCATION TYPE	SERVICE AREA
Hangar / Maintenance Facility	Not specified
LEAD TIME	EXPORT READY
Not specified	Not specified
WARRANTY	WARRANTY TERMS
Not specified	Not specified