ALERT: 26-GXGA - CRITICAL AOG

WANTED

Engine run-up support and ramp coordination

Item Id: PNYYH

GSE & Ramp Services - Boeing 737 MAX 8 - KMCO

Item Description

Provide ramp coordination and GSE support for engine motoring, starter and air valve functional checks, leak inspection, and controlled engine run-up after maintenance.

Item Details

PART / IPC REFERENCE **Not specified**	ALTERNATE PART NUMBERS **Not specified**
QUANTITY **Not specified**	REQUIRED ONSITE **30SEP26 1200Z**
REVISION **Not specified**	MANUFACTURER **Not specified**
MANUFACTURER TYPES **Not specified**	ACCEPTABLE MANUFACTURERS **Not specified**
AIRCRAFT MANUFACTURER **Not specified**	AIRCRAFT MODEL **Boeing 737 MAX 8**
ENGINE MANUFACTURER **Not specified**	ENGINE MODEL **LEAP-1B**
ATA 100 CHAPTERS 80 Starting	CONDITION **SV**
TRACE **Not specified**	RELEASE DOCUMENTATION **Not specified**
TRANSACTION TYPES **Not specified**	INCOTERM **Not specified**
ONSITE LOCATION TYPE **Ramp**	SERVICE AREA **Not specified**
LEAD TIME **Not specified**	EXPORT READY **Not specified**
WARRANTY **Not specified**	WARRANTY TERMS **Not specified**