

ALERT: 26-FPVH - ROUTINE MX EVENT

WANTED

Tow bar and ramp support

Item Id: EWNFH

GSE & Ramp Services - Boeing 737-800 - KOAK

Item Description

Provide compatible 737-800 tow bar, qualified tug operator, wing walkers, and ramp coordination for aircraft positioning before and after main landing gear exchange.

Item Details

PART / IPC REFERENCE	ALTERNATE PART NUMBERS
Not specified	Not specified
QUANTITY	REQUIRED ONSITE
Not specified	10OCT26 1400Z
REVISION	MANUFACTURER
Not specified	Not specified
MANUFACTURER TYPES	ACCEPTABLE MANUFACTURERS
Not specified	Not specified
AIRCRAFT MANUFACTURER	AIRCRAFT MODEL
Not specified	Boeing 737-800
ENGINE MANUFACTURER	ENGINE MODEL
Not specified	CFM56-7B
ATA 100 CHAPTERS	CONDITION
32 Landing Gear	TST
TRACE	RELEASE DOCUMENTATION
Not specified	Not specified
TRANSACTION TYPES	INCOTERM
Not specified	Not specified
ONSITE LOCATION TYPE	SERVICE AREA
Ramp	Not specified
LEAD TIME	EXPORT READY
Not specified	Not specified
WARRANTY	WARRANTY TERMS
Not specified	Not specified