

ALERT: 26-4EPU - ROUTINE MX EVENT

WANTED

Learjet landing-gear scheduled work - replacement component 1

Item Id: AQQ9C

Parts & Rotables - Beechcraft Hawker 400 / 400XP - KATL

Item Description

Traceable replacement material required for Learjet landing-gear scheduled work.

Item Details

PART / IPC REFERENCE	ALTERNATE PART NUMBERS
T330-MX-BIZ-2-1	Not specified
QUANTITY	REQUIRED ONSITE
1	19SEP26 1446Z
REVISION	MANUFACTURER
Not specified	Not specified
MANUFACTURER TYPES	ACCEPTABLE MANUFACTURERS
Not specified	Not specified
AIRCRAFT MANUFACTURER	AIRCRAFT MODEL
Not specified	Beechcraft Hawker 400 / 400XP
ENGINE MANUFACTURER	ENGINE MODEL
Not specified	PW600
ATA 100 CHAPTERS	CONDITION
20 Standard Practices - Airframe	Not specified
TRACE	RELEASE DOCUMENTATION
Not specified	Not specified
TRANSACTION TYPES	INCOTERM
Not specified	Not specified
ONSITE LOCATION TYPE	SERVICE AREA
Hangar / Maintenance Facility	Not specified
LEAD TIME	EXPORT READY
Not specified	Not specified
WARRANTY	WARRANTY TERMS
Not specified	Not specified