

ALERT: 26-4EPU - ROUTINE MX EVENT

Learjet landing-gear scheduled work

Beechcraft Hawker 400 / 400XP - PW600

Public Alert Information

STATUS

active

PRIORITY

ROUTINE

ICAO LOCATION

KATL

AIRCRAFT SERIES

Hawker 400 / 400XP

IMPACT TYPE

Charter

RTS TARGET

20SEP26 1445Z

ATA 100 CHAPTERS

5 - Time Limits / Maintenance Checks

20 Standard Practices - Airframe

24 Electrical Power

SERVICE BULLETIN (SB)

Not specified

SHORT FAULT NAME

Learjet landing-gear scheduled work

TROUBLESHOOTING STATUS

Troubleshooting Complete - All required Items listed

ROLES AND RESPONSIBILITIES

Responding provider supplies qualified personnel, material trace, and completion records.

ALERT TYPE

MX Alert

ADDED TO PLATFORM

16SEP26 1445Z

AIRCRAFT MODEL

Beechcraft Hawker 400 / 400XP

ENGINE MODEL

PW600

MX WINDOW OPENS

19SEP26 1445Z

ALERT SPECIFICS

Scheduled Maintenance

AIRWORTHINESS DIRECTIVE (AD)

Not specified

CHECK

Not specified

ERROR / FAULT INDICATIONS

Development scenario: Learjet landing-gear scheduled work; aircraft is unavailable pending corrective action.

TSM/FIM REFERENCE

T330-002

Learjet landing-gear scheduled work affecting a Beechcraft Hawker 400 / 400XP; Development test data requiring coordinated recovery support.

Page 1 of 2

Items (3)

MAINTENANCE SERVICES - WANTED

Qty Not specified

Learjet landing-gear scheduled work - support service 2

Item Id: HWQ4D

Qualified technical support required for Learjet landing-gear scheduled work.

PART / IPC REFERENCE	REQUIRED ONSITE
Not specified	19SEP26 1446Z
AIRCRAFT MODEL	ENGINE MODEL
Beechcraft Hawker 400 / 400XP	Not specified
ATA 100 CHAPTERS	CONDITION
24 Electrical Power	Not specified
TRACE	RELEASE DOCUMENTATION
Not specified	Not specified

TESTING & CERTIFICATION - WANTED

Qty Not specified

Learjet landing-gear scheduled work - support service 3

Item Id: TCHWQ

Qualified technical support required for Learjet landing-gear scheduled work.

PART / IPC REFERENCE	REQUIRED ONSITE
Not specified	19SEP26 1446Z
AIRCRAFT MODEL	ENGINE MODEL
Beechcraft Hawker 400 / 400XP	Not specified
ATA 100 CHAPTERS	CONDITION
5 - Time Limits / Maintenance Checks	Not specified
TRACE	RELEASE DOCUMENTATION
Not specified	Not specified

PARTS & ROTABLES - WANTED

Qty 1

Learjet landing-gear scheduled work - replacement component 1

Item Id: AQQ9C

Traceable replacement material required for Learjet landing-gear scheduled work.

PART / IPC REFERENCE	REQUIRED ONSITE
T330-MX-BIZ-2-1	19SEP26 1446Z
AIRCRAFT MODEL	ENGINE MODEL
Beechcraft Hawker 400 / 400XP	Not specified
ATA 100 CHAPTERS	CONDITION
20 Standard Practices - Airframe	Not specified
TRACE	RELEASE DOCUMENTATION
Not specified	Not specified

Status Updates (0)

No visible Status Updates.