

ALERT: 26-NHH7 - CRITICAL AOG

WANTED

Magnetic chip detector, LEAP-1B

Item Id: 97EU7

Parts & Rotables - Boeing 737 MAX 8 - KPHX

Item Description

Replacement MCD, new preferred

Item Details

PART / IPC REFERENCE	ALTERNATE PART NUMBERS
2555M78P01	Not specified
QUANTITY	REQUIRED ONSITE
1	25SEP26 1549Z
REVISION	MANUFACTURER
Latest	Not specified
MANUFACTURER TYPES	ACCEPTABLE MANUFACTURERS
Not specified	CFM International
AIRCRAFT MANUFACTURER	AIRCRAFT MODEL
Not specified	Boeing 737 MAX 8
ENGINE MANUFACTURER	ENGINE MODEL
Not specified	LEAP-1B
ATA 100 CHAPTERS	CONDITION
79 Oil	NE
TRACE	RELEASE DOCUMENTATION
OEM trace, Maintenance release trace	FAA Form 8130-3
TRANSACTION TYPES	INCOTERM
Outright Purchase	DAP
ONSITE LOCATION TYPE	SERVICE AREA
Hangar / Maintenance Facility	Not specified
LEAD TIME	EXPORT READY
Not specified	Not specified
WARRANTY	WARRANTY TERMS
No	Not specified