ALERT: 26-TTPY - EXPEDITE MX EVENT

WANTED

APU change crew, FAA A&P

Item Id: YRGKV

Maintenance Services - Boeing 737-800 - KATL

Item Description

Provide a three-person FAA A&P crew with 737NG experience for APU removal, installation, leak checks, and APU run.

Item Details

PART / IPC REFERENCE **Not specified**	ALTERNATE PART NUMBERS **Not specified**
QUANTITY **Not specified**	REQUIRED ONSITE **14OCT26 0300Z**
REVISION **Not specified**	MANUFACTURER **Not specified**
MANUFACTURER TYPES **Not specified**	ACCEPTABLE MANUFACTURERS **Not specified**
AIRCRAFT MANUFACTURER **Not specified**	AIRCRAFT MODEL **Boeing 737-800**
ENGINE MANUFACTURER **Not specified**	ENGINE MODEL **CFM56-7B**
ATA 100 CHAPTERS 49 Airborne Auxiliary Power	CONDITION **SV**
TRACE **Not specified**	RELEASE DOCUMENTATION **Not specified**
TRANSACTION TYPES **Not specified**	INCOTERM **Not specified**
ONSITE LOCATION TYPE **Hangar / Maintenance Facility**	SERVICE AREA **Not specified**
LEAD TIME **Not specified**	EXPORT READY **Not specified**
WARRANTY **Not specified**	WARRANTY TERMS **Not specified**