

ALERT: 26-TTPY - EXPEDITE MX EVENT

WANTED

APU change crew, FAA A&P

Item Id: YRGKV
Maintenance Services - Boeing 737-800 - KATL

Item Description

Provide a three-person FAA A&P crew with 737NG experience for APU removal, installation, leak checks, and APU run.

Item Details	
PART / IPC REFERENCE	ALTERNATE PART NUMBERS
Not specified	Not specified
QUANTITY	REQUIRED ONSITE
Not specified	14OCT26 0300Z
REVISION	MANUFACTURER
Not specified	Not specified
MANUFACTURER TYPES	ACCEPTABLE MANUFACTURERS
Not specified	Not specified
AIRCRAFT MANUFACTURER	AIRCRAFT MODEL
Not specified	Boeing 737-800
ENGINE MANUFACTURER	ENGINE MODEL
Not specified	CFM56-7B
ATA 100 CHAPTERS	CONDITION
49 Airborne Auxiliary Power	SV
TRACE	RELEASE DOCUMENTATION
Not specified	Not specified
TRANSACTION TYPES	INCOTERM
Not specified	Not specified
ONSITE LOCATION TYPE	SERVICE AREA
Hangar / Maintenance Facility	Not specified
LEAD TIME	EXPORT READY
Not specified	Not specified
WARRANTY	WARRANTY TERMS
Not specified	Not specified