ALERT: 26-TTPY - EXPEDITE MX EVENT

737-800 A-check with APU replacement at KATL

Boeing 737-800 - CFM56-7B

Public Alert Information

STATUS
active

ALERT TYPE
MX Alert

PRIORITY
EXPEDITE

ADDED TO PLATFORM
29SEP26 0926Z

ICAO LOCATION
KATL

AIRCRAFT MODEL
Boeing 737-800

AIRCRAFT SERIES
Not specified

ENGINE MODEL
CFM56-7B

IMPACT TYPE
Revenue PAX

MX WINDOW OPENS
14OCT26 0300Z

RTS TARGET
15OCT26 1100Z

ALERT SPECIFICS
Check (A/B/C/D), Scheduled Maintenance

ATA 100 CHAPTERS
49 Airborne Auxiliary Power

AIRWORTHINESS DIRECTIVE (AD)
Not specified

SERVICE BULLETIN (SB)
Not specified

CHECK
A

SHORT FAULT NAME
Scheduled A-check with APU replacement

ERROR / FAULT INDICATIONS
APU EGT margin trend below planning limit. APU replacement scheduled with the A-check to avoid an unscheduled removal.

TROUBLESHOOTING STATUS
Troubleshooting Complete - All required Items listed

TSM/FIM REFERENCE
Not specified

ROLES AND RESPONSIBILITIES
Southwest maintenance planning controls the A-check package and release. Contract A&P mechanics perform APU removal and installation. Supplier provides the exchange APU and lifting equipment.

Southwest seeks an exchange APU, lifting equipment, and technicians for an APU replacement during a scheduled 737-800 A-check at KATL. Work window opens 14 October with return to service the next morning.

Items (3)

TOOLS, FIXTURES, & TMDE - WANTED

Qty 1

APU removal and installation hoist kit

Item Id: XMGR9

Provide a 737NG APU hoist kit and cradle with current load certification for APU removal and installation.

PART / IPC REFERENCE **737NG-APU-HOIST-KIT**	REQUIRED ONSITE **13OCT26 2200Z**
AIRCRAFT MODEL **Not specified**	ENGINE MODEL **Not specified**
ATA 100 CHAPTERS 49 Airborne Auxiliary Power	CONDITION **SV**
TRACE **OEM trace**	RELEASE DOCUMENTATION **FAA Form 8130-3**

MAINTENANCE SERVICES - WANTED

Qty Not specified

APU change crew, FAA A&P

Item Id: YRGKV

Provide a three-person FAA A&P crew with 737NG experience for APU removal, installation, leak checks, and APU run.

PART / IPC REFERENCE **Not specified**	REQUIRED ONSITE **14OCT26 0300Z**
AIRCRAFT MODEL **Boeing 737-800**	ENGINE MODEL **Not specified**
ATA 100 CHAPTERS 49 Airborne Auxiliary Power	CONDITION **SV**
TRACE **Not specified**	RELEASE DOCUMENTATION **Not specified**

PARTS & ROTABLES - WANTED

Qty 1

APU exchange unit, 131-9B

Item Id: MDVUT

Overhauled Honeywell 131-9B APU for 737NG, dressed with standard accessories.

PART / IPC REFERENCE **3800298-1**	REQUIRED ONSITE **13OCT26 2000Z**
AIRCRAFT MODEL **Not specified**	ENGINE MODEL **Not specified**
ATA 100 CHAPTERS 49 Airborne Auxiliary Power	CONDITION **OH**
TRACE **OEM trace**	RELEASE DOCUMENTATION **FAA Form 8130-3**

Status Updates (0)

No visible Status Updates.