

ALERT: 26-TTPY - EXPEDITE MX EVENT

737-800 A-check with APU replacement at KATL

Boeing 737-800 - CFM56-7B

Public Alert Information	
STATUS active	ALERT TYPE MX Alert
PRIORITY EXPEDITE	ADDED TO PLATFORM 29SEP26 0926Z
ICAO LOCATION KATL	AIRCRAFT MODEL Boeing 737-800
AIRCRAFT SERIES Not specified	ENGINE MODEL CFM56-7B
IMPACT TYPE Revenue PAX	MX WINDOW OPENS 14OCT26 0300Z
RTS TARGET 15OCT26 1100Z	ALERT SPECIFICS Check (A/B/C/D), Scheduled Maintenance
ATA 100 CHAPTERS 49 Airborne Auxiliary Power	AIRWORTHINESS DIRECTIVE (AD) Not specified
SERVICE BULLETIN (SB) Not specified	CHECK A
SHORT FAULT NAME Scheduled A-check with APU replacement	ERROR / FAULT INDICATIONS APU EGT margin trend below planning limit. APU replacement scheduled with the A-check to avoid an unscheduled removal.
TROUBLESHOOTING STATUS Troubleshooting Complete - All required Items listed	TSM/FIM REFERENCE Not specified
ROLES AND RESPONSIBILITIES Southwest maintenance planning controls the A-check package and release. Contract A&P mechanics perform APU removal and installation. Supplier provides the exchange APU and lifting equipment.	
Southwest seeks an exchange APU, lifting equipment, and technicians for an APU replacement during a scheduled 737-800 A-check at KATL. Work window opens 14 October with return to service the next morning.	

Items (3)

TOOLS, FIXTURES, & TMDE - WANTED

Qty 1

APU removal and installation hoist kit

Item Id: XMGR9

Provide a 737NG APU hoist kit and cradle with current load certification for APU removal and installation.

PART / IPC REFERENCE	REQUIRED ONSITE
737NG-APU-HOIST-KIT	13OCT26 2200Z
AIRCRAFT MODEL	ENGINE MODEL
Not specified	Not specified
ATA 100 CHAPTERS	CONDITION
49 Airborne Auxiliary Power	SV
TRACE	RELEASE DOCUMENTATION
OEM trace	FAA Form 8130-3

MAINTENANCE SERVICES - WANTED

Qty Not specified

APU change crew, FAA A&P

Item Id: YRGKV

Provide a three-person FAA A&P crew with 737NG experience for APU removal, installation, leak checks, and APU run.

PART / IPC REFERENCE	REQUIRED ONSITE
Not specified	14OCT26 0300Z
AIRCRAFT MODEL	ENGINE MODEL
Boeing 737-800	Not specified
ATA 100 CHAPTERS	CONDITION
49 Airborne Auxiliary Power	SV
TRACE	RELEASE DOCUMENTATION
Not specified	Not specified

PARTS & ROTABLES - WANTED

Qty 1

APU exchange unit, 131-9B

Item Id: MDVUT

Overhauled Honeywell 131-9B APU for 737NG, dressed with standard accessories.

PART / IPC REFERENCE	REQUIRED ONSITE
3800298-1	13OCT26 2000Z
AIRCRAFT MODEL	ENGINE MODEL
Not specified	Not specified
ATA 100 CHAPTERS	CONDITION
49 Airborne Auxiliary Power	OH
TRACE	RELEASE DOCUMENTATION
OEM trace	FAA Form 8130-3

Status Updates (0)

No visible Status Updates.