ALERT: 26-HCXF - CRITICAL AOG

737 MAX 8 flight control computer B fault at KSJC

Boeing 737 MAX 8 - LEAP-1B

Public Alert Information

STATUS
active

ALERT TYPE
AOG Alert

PRIORITY
CRITICAL

ADDED TO PLATFORM
29SEP26 0920Z

ICAO LOCATION
KSJC

AIRCRAFT MODEL
Boeing 737 MAX 8

AIRCRAFT SERIES
Not specified

ENGINE MODEL
LEAP-1B

IMPACT TYPE
Revenue PAX

MX WINDOW OPENS
29SEP26 0710Z

RTS TARGET
30SEP26 2000Z

ALERT SPECIFICS
Unscheduled Maintenance

ATA 100 CHAPTERS
22 Auto Flight

AIRWORTHINESS DIRECTIVE (AD)
Not specified

SERVICE BULLETIN (SB)
Not specified

CHECK
Not specified

SHORT FAULT NAME
FCC B self-check failure

ERROR / FAULT INDICATIONS
FCC B fault on the maintenance page with autopilot B unavailable. FCC B fails power-up self-check after circuit breaker reset.

TROUBLESHOOTING STATUS
Troubleshooting Complete - All required Items listed

TSM/FIM REFERENCE
Not specified

ROLES AND RESPONSIBILITIES
Southwest MCC coordinates parts and aircraft release. Avionics technician replaces FCC B and loads software. Courier provider delivers the unit to KSJC ramp.

Southwest 737 MAX 8 at KSJC is held for a flight control computer B fault found during power-up. FCC B fails its self-check and the aircraft cannot dispatch, requiring an FCC replacement, avionics support, and expedited logistics.

Items (3)

PARTS & ROTABLES - WANTED

Qty 1

Flight control computer, FCC B

Item Id: JXW49

Serviceable 737 MAX flight control computer with current software standard, preserved for installation.

PART / IPC REFERENCE **822-2240-102**	REQUIRED ONSITE **30SEP26 0600Z**
AIRCRAFT MODEL **Not specified**	ENGINE MODEL **Not specified**
ATA 100 CHAPTERS 22 Auto Flight	CONDITION **SV**
TRACE **OEM trace**	RELEASE DOCUMENTATION **FAA Form 8130-3**

LOGISTICS & CUSTOMS - WANTED

Qty Not specified

AOG next-flight-out courier to KSJC

Item Id: 3PUPF

Arrange next-flight-out transport of the FCC to KSJC with priority handling, tracking, and tail-side delivery.

PART / IPC REFERENCE **Not specified**	REQUIRED ONSITE **30SEP26 0600Z**
AIRCRAFT MODEL **Boeing 737 MAX 8**	ENGINE MODEL **Not specified**
ATA 100 CHAPTERS 22 Auto Flight	CONDITION **SV**
TRACE **Not specified**	RELEASE DOCUMENTATION **Not specified**

MAINTENANCE SERVICES - WANTED

Qty Not specified

Avionics technician onsite, FAA A&P

Item Id: 9FJA9

Provide a 737 MAX avionics technician for FCC removal and installation, software load, autopilot and stab trim operational checks.

PART / IPC REFERENCE **Not specified**	REQUIRED ONSITE **30SEP26 0600Z**
AIRCRAFT MODEL **Boeing 737 MAX 8**	ENGINE MODEL **Not specified**
ATA 100 CHAPTERS 22 Auto Flight	CONDITION **SV**
TRACE **Not specified**	RELEASE DOCUMENTATION **Not specified**

Status Updates (0)

No visible Status Updates.