ALERT: 26-QCX4 - ROUTINE MX EVENT

WANTED

HPT stage 1 borescope inspection, both engines

Item Id: V9DVG

Testing & Certification - Boeing 787-10 - EHAM

Item Description

Perform SB borescope inspection of HPT stage 1 blades on both GEnx-1B engines with image capture and a findings report formatted for GE disposition.

Item Details

PART / IPC REFERENCE
Not specified

ALTERNATE PART NUMBERS
Not specified

QUANTITY
Not specified

REQUIRED ONSITE
19OCT26 2000Z

REVISION
Not specified

MANUFACTURER
Not specified

MANUFACTURER TYPES
Not specified

ACCEPTABLE MANUFACTURERS
Not specified

AIRCRAFT MANUFACTURER
Not specified

AIRCRAFT MODEL
Boeing 787-10

ENGINE MANUFACTURER
Not specified

ENGINE MODEL
GEnx-1B

ATA 100 CHAPTERS
72 Engine

CONDITION
SV

TRACE
Not specified

RELEASE DOCUMENTATION
Not specified

TRANSACTION TYPES
Not specified

INCOTERM
Not specified

ONSITE LOCATION TYPE
Hangar / Maintenance Facility

SERVICE AREA
Not specified

LEAD TIME
Not specified

EXPORT READY
Not specified

WARRANTY
Not specified

WARRANTY TERMS
Not specified