

ALERT: 26-QCX4 - ROUTINE MX EVENT

WANTED

HPT stage 1 borescope inspection, both engines

Item Id: V9DVG

Testing & Certification - Boeing 787-10 - EHAM

Item Description

Perform SB borescope inspection of HPT stage 1 blades on both GEnx-1B engines with image capture and a findings report formatted for GE disposition.

Item Details

PART / IPC REFERENCE	ALTERNATE PART NUMBERS
Not specified	Not specified
QUANTITY	REQUIRED ONSITE
Not specified	19OCT26 2000Z
REVISION	MANUFACTURER
Not specified	Not specified
MANUFACTURER TYPES	ACCEPTABLE MANUFACTURERS
Not specified	Not specified
AIRCRAFT MANUFACTURER	AIRCRAFT MODEL
Not specified	Boeing 787-10
ENGINE MANUFACTURER	ENGINE MODEL
Not specified	GEnx-1B
ATA 100 CHAPTERS	CONDITION
72 Engine	SV
TRACE	RELEASE DOCUMENTATION
Not specified	Not specified
TRANSACTION TYPES	INCOTERM
Not specified	Not specified
ONSITE LOCATION TYPE	SERVICE AREA
Hangar / Maintenance Facility	Not specified
LEAD TIME	EXPORT READY
Not specified	Not specified
WARRANTY	WARRANTY TERMS
Not specified	Not specified