

ALERT: 26-QCX4 - ROUTINE MX EVENT

WANTED

EASA Part-66 B1 technicians, 787 GEnx

Item Id: MPJEM

Maintenance Services - Boeing 787-10 - EHAM

Item Description

Provide two EASA B1 technicians with 787 GEnx type rating for engine access, core turning, cowl closure, and CRS.

Item Details	
PART / IPC REFERENCE	ALTERNATE PART NUMBERS
Not specified	Not specified
QUANTITY	REQUIRED ONSITE
Not specified	19OCT26 2000Z
REVISION	MANUFACTURER
Not specified	Not specified
MANUFACTURER TYPES	ACCEPTABLE MANUFACTURERS
Not specified	Not specified
AIRCRAFT MANUFACTURER	AIRCRAFT MODEL
Not specified	Boeing 787-10
ENGINE MANUFACTURER	ENGINE MODEL
Not specified	GEnx-1B
ATA 100 CHAPTERS	CONDITION
72 Engine	SV
TRACE	RELEASE DOCUMENTATION
Not specified	Not specified
TRANSACTION TYPES	INCOTERM
Not specified	Not specified
ONSITE LOCATION TYPE	SERVICE AREA
Hangar / Maintenance Facility	Not specified
LEAD TIME	EXPORT READY
Not specified	Not specified
WARRANTY	WARRANTY TERMS
Not specified	Not specified