ALERT: 26-QCX4 - ROUTINE MX EVENT

WANTED

EASA Part-66 B1 technicians, 787 GEnx

Item Id: MPJEM

Maintenance Services - Boeing 787-10 - EHAM

Item Description

Provide two EASA B1 technicians with 787 GEnx type rating for engine access, core turning, cowl closure, and CRS.

Item Details

PART / IPC REFERENCE **Not specified**	ALTERNATE PART NUMBERS **Not specified**
QUANTITY **Not specified**	REQUIRED ONSITE **19OCT26 2000Z**
REVISION **Not specified**	MANUFACTURER **Not specified**
MANUFACTURER TYPES **Not specified**	ACCEPTABLE MANUFACTURERS **Not specified**
AIRCRAFT MANUFACTURER **Not specified**	AIRCRAFT MODEL **Boeing 787-10**
ENGINE MANUFACTURER **Not specified**	ENGINE MODEL **GEnx-1B**
ATA 100 CHAPTERS 72 Engine	CONDITION **SV**
TRACE **Not specified**	RELEASE DOCUMENTATION **Not specified**
TRANSACTION TYPES **Not specified**	INCOTERM **Not specified**
ONSITE LOCATION TYPE **Hangar / Maintenance Facility**	SERVICE AREA **Not specified**
LEAD TIME **Not specified**	EXPORT READY **Not specified**
WARRANTY **Not specified**	WARRANTY TERMS **Not specified**