ALERT: 26-QCX4 - ROUTINE MX EVENT

787-10 GEnx-1B HPT borescope per SB at EHAM

Boeing 787-10 - GEnx-1B

Public Alert Information

STATUS
active

ALERT TYPE
MX Alert

PRIORITY
ROUTINE

ADDED TO PLATFORM
29SEP26 1037Z

ICAO LOCATION
EHAM

AIRCRAFT MODEL
Boeing 787-10

AIRCRAFT SERIES
Not specified

ENGINE MODEL
GEnx-1B

IMPACT TYPE
Revenue PAX

MX WINDOW OPENS
19OCT26 2000Z

RTS TARGET
21OCT26 0500Z

ALERT SPECIFICS
Scheduled Maintenance, Service Bulletin (SB)

ATA 100 CHAPTERS
72 Engine

AIRWORTHINESS DIRECTIVE (AD)
Not specified

SERVICE BULLETIN (SB)
GE SB GEnx-1B 72-0453 Rev 02

CHECK
Not specified

SHORT FAULT NAME
GEnx-1B HPT stage 1 blade SB borescope

ERROR / FAULT INDICATIONS
Repeat SB borescope inspection of HPT stage 1 blades on engines 1 and 2, due at the next cycle threshold.

TROUBLESHOOTING STATUS
Troubleshooting Complete - All required Items listed

TSM/FIM REFERENCE
Not specified

ROLES AND RESPONSIBILITIES
KLM Engineering and Maintenance controls the SB package and release. Borescope provider performs inspection and reporting. Contract B1 technicians handle access and closure.

KLM seeks borescope capability and GEnx-rated technicians for a service bulletin inspection of HPT stage 1 blades on both engines of a 787-10 at EHAM. Work window opens 19 October on an overnight ground time.

Items (3)

TESTING & CERTIFICATION - WANTED

Qty Not specified

HPT stage 1 borescope inspection, both engines

Item Id: V9DVG

Perform SB borescope inspection of HPT stage 1 blades on both GEnx-1B engines with image capture and a findings report formatted for GE disposition.

PART / IPC REFERENCE **Not specified**	REQUIRED ONSITE **19OCT26 2000Z**
AIRCRAFT MODEL **Boeing 787-10**	ENGINE MODEL **Not specified**
ATA 100 CHAPTERS 72 Engine	CONDITION **SV**
TRACE **Not specified**	RELEASE DOCUMENTATION **Not specified**

TOOLS, FIXTURES, & TMDE - WANTED

Qty 1

Video borescope kit with GEnx guide tube set, rental

Item Id: QKXV7

Rental of a video borescope with articulating probe and GEnx-1B HPT guide tube set, calibrated and ready for use.

PART / IPC REFERENCE **VBS-GENX-1B-KIT**	REQUIRED ONSITE **19OCT26 1800Z**
AIRCRAFT MODEL **Not specified**	ENGINE MODEL **Not specified**
ATA 100 CHAPTERS 72 Engine	CONDITION **SV**
TRACE **OEM trace**	RELEASE DOCUMENTATION **EASA Form 1**

MAINTENANCE SERVICES - WANTED

Qty Not specified

EASA Part-66 B1 technicians, 787 GEnx

Item Id: MPJEM

Provide two EASA B1 technicians with 787 GEnx type rating for engine access, core turning, cowl closure, and CRS.

PART / IPC REFERENCE **Not specified**	REQUIRED ONSITE **19OCT26 2000Z**
AIRCRAFT MODEL **Boeing 787-10**	ENGINE MODEL **Not specified**
ATA 100 CHAPTERS 72 Engine	CONDITION **SV**
TRACE **Not specified**	RELEASE DOCUMENTATION **Not specified**

Status Updates (0)

No visible Status Updates.