ALERT: 26-73E7 - ROUTINE MX EVENT

WANTED

Challenger corrosion inspection - replacement component 1

Item Id: 99JYY

Parts & Rotables - Bombardier Learjet 40 / 45 - KATL

Item Description

Traceable replacement material required for Challenger corrosion inspection.

Item Details

PART / IPC REFERENCE **T330-MX-BIZ-5-1**	ALTERNATE PART NUMBERS **Not specified**
QUANTITY **1**	REQUIRED ONSITE **22SEP26 1446Z**
REVISION **Not specified**	MANUFACTURER **Not specified**
MANUFACTURER TYPES **Not specified**	ACCEPTABLE MANUFACTURERS **Not specified**
AIRCRAFT MANUFACTURER **Not specified**	AIRCRAFT MODEL **Bombardier Learjet 40 / 45**
ENGINE MANUFACTURER **Not specified**	ENGINE MODEL **PW600**
ATA 100 CHAPTERS 24 Electrical Power	CONDITION **Not specified**
TRACE **Not specified**	RELEASE DOCUMENTATION **Not specified**
TRANSACTION TYPES **Not specified**	INCOTERM **Not specified**
ONSITE LOCATION TYPE **Hangar / Maintenance Facility**	SERVICE AREA **Not specified**
LEAD TIME **Not specified**	EXPORT READY **Not specified**
WARRANTY **Not specified**	WARRANTY TERMS **Not specified**