ALERT: 26-97GW - CRITICAL AOG

WANTED

On-site Gulfstream flight controls diagnosis — rudder restriction

Item Id: HRYGK

Maintenance Services - Gulfstream G550 - KCAG

Item Description

Need Gulfstream-experienced A&P (prefer G550) at KCAG for fault isolation of rudder restriction. No parts identified yet. Provide troubleshooting labor, tooling, and recommended corrective action / parts after diagnosis. On-site KCAG ASAP / within next 24h Zulu; Hangar or Ramp.

Item Details

PART / IPC REFERENCE **Not specified**	ALTERNATE PART NUMBERS **Not specified**
QUANTITY **Not specified**	REQUIRED ONSITE **23SEP26 0829Z**
REVISION **Not specified**	MANUFACTURER **Not specified**
MANUFACTURER TYPES **Not specified**	ACCEPTABLE MANUFACTURERS **Not specified**
AIRCRAFT MANUFACTURER **Not specified**	AIRCRAFT MODEL **Gulfstream G550**
ENGINE MANUFACTURER **Not specified**	ENGINE MODEL **BR710**
ATA 100 CHAPTERS 27 Flight Controls	CONDITION **SC**
TRACE **Not specified**	RELEASE DOCUMENTATION **Not specified**
TRANSACTION TYPES **Not specified**	INCOTERM **Not specified**
ONSITE LOCATION TYPE **Hangar / Maintenance Facility**	SERVICE AREA **Not specified**
LEAD TIME **Not specified**	EXPORT READY **Not specified**
WARRANTY **Not specified**	WARRANTY TERMS **Not specified**