ALERT: 26-97GW - CRITICAL AOG

Gulfstream rudder restriction - KCAG

Gulfstream G550 - BR710

Public Alert Information

STATUS
active

ALERT TYPE
AOG Alert

PRIORITY
CRITICAL

ADDED TO PLATFORM
22SEP26 0831Z

ICAO LOCATION
KCAG

AIRCRAFT MODEL
Gulfstream G550

AIRCRAFT SERIES
Not specified

ENGINE MODEL
BR710

IMPACT TYPE
Charter

MX WINDOW OPENS
22SEP26 0829Z

RTS TARGET
24SEP26 0829Z

ALERT SPECIFICS
Unscheduled Maintenance

ATA 100 CHAPTERS
27 Flight Controls

AIRWORTHINESS DIRECTIVE (AD)
Not specified

SERVICE BULLETIN (SB)
Not specified

CHECK
Not specified

SHORT FAULT NAME
Rudder restriction

ERROR / FAULT INDICATIONS
Crew reported restricted rudder feel / limited travel on ground check; no CAS text confirmed yet

TROUBLESHOOTING STATUS
Troubleshooting Not Started

TSM/FIM REFERENCE
Not specified

ROLES AND RESPONSIBILITIES
MCC coordinates; Station MX / contracted Gulfstream tech performs diagnosis; Materials on standby for parts after fault isolation

Charter aircraft AOG at Craig, CO (KCAG) with reported rudder restriction. Troubleshooting not started; seeking qualified Gulfstream diagnostic / flight-controls support on site. Parts list TBD pending diagnosis.

Items (1)

MAINTENANCE SERVICES - WANTED

Qty Not specified

On-site Gulfstream flight controls diagnosis — rudder restriction

Item Id: HRYGK

Need Gulfstream-experienced A&P (prefer G550) at KCAG for fault isolation of rudder restriction. No parts identified yet. Provide troubleshooting labor, tooling, and recommended corrective action / parts after diagnosis. On-site KCAG ASAP / within next 24h Zulu; Hangar or Ramp.

PART / IPC REFERENCE **Not specified**	REQUIRED ONSITE **23SEP26 0829Z**
AIRCRAFT MODEL **Gulfstream G550**	ENGINE MODEL **Not specified**
ATA 100 CHAPTERS 27 Flight Controls	CONDITION **SC**
TRACE **Not specified**	RELEASE DOCUMENTATION **Not specified**

Status Updates (0)

No visible Status Updates.