

ALERT: 26-97GW - CRITICAL AOG

Gulfstream rudder restriction - KCAG

Gulfstream G550 - BR710

Public Alert Information

STATUS	active	ALERT TYPE	AOG Alert
PRIORITY	CRITICAL	ADDED TO PLATFORM	22SEP26 0831Z
ICAO LOCATION	KCAG	AIRCRAFT MODEL	Gulfstream G550
AIRCRAFT SERIES	Not specified	ENGINE MODEL	BR710
IMPACT TYPE	Charter	MX WINDOW OPENS	22SEP26 0829Z
RTS TARGET	24SEP26 0829Z	ALERT SPECIFICS	Unscheduled Maintenance
ATA 100 CHAPTERS	27 Flight Controls	AIRWORTHINESS DIRECTIVE (AD)	Not specified
SERVICE BULLETIN (SB)	Not specified	CHECK	Not specified
SHORT FAULT NAME	Rudder restriction	ERROR / FAULT INDICATIONS	Crew reported restricted rudder feel / limited travel on ground check; no CAS text confirmed yet
TROUBLESHOOTING STATUS	Troubleshooting Not Started	TSM/FIM REFERENCE	Not specified
ROLES AND RESPONSIBILITIES	MCC coordinates; Station MX / contracted Gulfstream tech performs diagnosis; Materials on standby for parts after fault isolation		

Charter aircraft AOG at Craig, CO (KCAG) with reported rudder restriction. Troubleshooting not started; seeking qualified Gulfstream diagnostic / flight-controls support on site. Parts list TBD pending diagnosis.

Items (1)

MAINTENANCE SERVICES - WANTED

Qty Not specified

On-site Gulfstream flight controls diagnosis — rudder restriction

Item Id: HRYGK

Need Gulfstream-experienced A&P (prefer G550) at KCAG for fault isolation of rudder restriction. No parts identified yet. Provide troubleshooting labor, tooling, and recommended corrective action / parts after diagnosis. On-site KCAG ASAP / within next 24h Zulu; Hangar or Ramp.

PART / IPC REFERENCE	REQUIRED ONSITE
Not specified	23SEP26 0829Z
AIRCRAFT MODEL	ENGINE MODEL
Gulfstream G550	Not specified
ATA 100 CHAPTERS	CONDITION
27 Flight Controls	SC
TRACE	RELEASE DOCUMENTATION
Not specified	Not specified

Status Updates (0)

No visible Status Updates.