

ALERT: 26-9NG4 - CRITICAL AOG

Hydraulic leak A320

Airbus A320 - CFM56-5B

Public Alert Information

STATUS

active

PRIORITY

CRITICAL

ICAO LOCATION

KDAL

AIRCRAFT SERIES

ceo

IMPACT TYPE

Revenue PAX

RTS TARGET

23SEP26 1558Z

ATA 100 CHAPTERS

29

Hydraulic Power

SERVICE BULLETIN (SB)

Not specified

SHORT FAULT NAME

Hydraulic system leak

TROUBLESHOOTING STATUS

Troubleshooting Incomplete - Additional Items may be required

ROLES AND RESPONSIBILITIES

MCC owns troubleshooting; Station MX installs; Materials sources parts

ALERT TYPE

AOG Alert

ADDED TO PLATFORM

21SEP26 1600Z

AIRCRAFT MODEL

Airbus A320

ENGINE MODEL

CFM56-5B

MX WINDOW OPENS

21SEP26 1558Z

ALERT SPECIFICS

Unscheduled Maintenance

AIRWORTHINESS DIRECTIVE (AD)

Not specified

CHECK

Not specified

ERROR / FAULT INDICATIONS

HYD SYS LO PRESS; yellow HYD caution; visible fluid under belly fairing

TSM/FIM REFERENCE

TSM 29-XX-00 (TEST)

Simulated AOG for marketplace UX testing. Not a real aircraft event.

Page 1 of 3

Items (4)

PARTS & ROTABLES - WANTED

Qty 1

TEST — Hydraulic hose assembly

Item Id: AARR3

TEST DATA. Flexible HYD hose assembly, on-wing replace. Wanted new or OH.

PART / IPC REFERENCE

AS621-08-0160

REQUIRED ONSITE

22SEP26 2000Z

AIRCRAFT MODEL

Not specified

ENGINE MODEL

Not specified

ATA 100 CHAPTERS

29

Hydraulic Power

CONDITION

NE, OH, SV

TRACE

OEM trace

RELEASE DOCUMENTATION

FAA Form 8130-3

PARTS & ROTABLES - WANTED

Qty 2

TEST — Hydraulic filter element

Item Id: ARUCV

TEST DATA. Pressure filter element for HYD system. Prefer OEM.

PART / IPC REFERENCE

LE8979A1

REQUIRED ONSITE

22SEP26 2000Z

AIRCRAFT MODEL

Not specified

ENGINE MODEL

Not specified

ATA 100 CHAPTERS

29

Hydraulic Power

CONDITION

OH, SV

TRACE

OEM trace

RELEASE DOCUMENTATION

FAA Form 8130-3

PARTS & ROTABLES - WANTED

Qty 1

TEST — Engine-driven hydraulic pump (wanted)

Item Id: 37WGN

TEST — Engine-driven hydraulic pump (wanted)

PART / IPC REFERENCE

3031864

REQUIRED ONSITE

22SEP26 2000Z

AIRCRAFT MODEL

Not specified

ENGINE MODEL

Not specified

ATA 100 CHAPTERS

29

Hydraulic Power

CONDITION

OH

TRACE

OEM trace

RELEASE DOCUMENTATION

FAA Form 8130-3

TEST — Hydraulic reservoir (yellow system)

Item Id: 9MCNH

TEST DATA. Yellow hydraulic system reservoir for A320. Wanted OH/SV with 8130-3.

PART / IPC REFERENCE	REQUIRED ONSITE
D23379000	22SEP26 2000Z
AIRCRAFT MODEL	ENGINE MODEL
Not specified	Not specified
ATA 100 CHAPTERS	CONDITION
29 Hydraulic Power	OH, SV
TRACE	RELEASE DOCUMENTATION
OEM trace	FAA Form 8130-3

Status Updates (0)

No visible Status Updates.